• NOISE—"CHATTERING" FROM REAR AXLE HEARD ON TURNS OR WHEN CORNERING—VEHICLES WITH LIMITED SLIP AXLE • AXLE—LIMITED SLIP—REAR AXLE "CHATTERING" NOISE ON TURNS OR WHEN CORNERING	**Article No. 00-8-4**

FORD: 1999-2000 E-150, EXPEDITION, F-150

LINCOLN: 1999-2000 NAVIGATOR

ISSUE

A "chattering" noise from the rear axle may be heard when turning or cornering. This may be due to differentials containing clutch packs that have been gauged too tightly.

ACTION

Install new Traction-Lok Clutch Pack Kit. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Confirm axle chatter with road test.
2. Once axle chatter has been confirmed, remove and discard old clutch packs, shims and Belleville springs. Refer to the appropriate Workshop Manual for details.

NOTE

SUBTRACT 0.25mm (0.010″) FROM FEELER GAUGE READING TAKEN DURING SHIM SELECTION USING SERVICE TOOLS AND PROCEDURES INDICATED ON INSTRUCTION SHEETS PACKAGED WITH KITS.

3. Install Clutch Pack Kit F75Z-4947-AA for 9.75″ ring gear Traction-Lok axles or Clutch Pack Kit F75Z-4947-AB for 10.25 ″ ring gear Traction-Lok axles. For ring gear size and differential type, see embossed metal tag attached to rear axle cover. Refer to the appropriate Workshop Manual for details.

PART NUMBER	PART NAME
F75Z-4947-AA	Clutch Pack Kit (9.75″ Ring Gear)
F75Z-4947-AB	Clutch Pack Kit (10.25″ Ring Gear)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
000804A	Install Clutch Pack (Drum Brake Applications)	2.2 Hrs.
000804B	Install Clutch Pack (Disc Brake Applications Without Air Suspension)	2.4 Hrs.
000804C	Install Clutch Pack (Disc Brake Applications With Air Suspension)	2.5 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
4026	42

OASIS CODES: 509000, 510000, 597997, 702000, 702200