Ford Motor Company

Service Recall Bulletin

July 2000

TO: All Ford Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD: Safety Recall 00S12: Certain 2000 Model Year F-53 Motorhome Stripped Chassis – Push Rod Brake Retainer Clip Inspection / Installation

AFFECTED VEHICLES

Certain 2000 model year F-53 motorhome stripped chassis built at the TruMack Assembly Plant from November 9, 1999 through April 29, 2000.

NOTE: All of the vehicles affected by Safety Recall 00S12 are also affected by Owner Notification Program 00B48. Please complete both programs at the same time. Customers will be notified about both programs in one letter.

SAFETY CONCERN

The brake pedal to hydraulic booster pushrod retainer pin on a small number of the affected vehicles may not have been properly installed on the service brake pedal. Improperly installed or missing retainers could result in loss of service braking capability. This could occur without warning and result in an accident. The vehicle parking brake system is not affected and remains operational.

SERVICE ACTION

The dealer must inspect the push rod brake retainer clip to make sure it is properly seated. If the retainer clip is missing the dealership must install a new brake retainer clip. This service action must be completed before demonstrating or delivering any of the vehicles involved in this recall.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $1,100 per vehicle.

ATTACHMENTS

Attachment I:	Administrative Information
Attachment II:	Labor Allowances and Parts Ordering Information
Attachment III:	Technical Information
Attachment IV:	Customer Letter

QUESTIONS?

Claims Information: ……1-800-423-8851
Other (Dealer Only) Recall Questions: ……...1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

DEMONSTRATION / DELIVERY HOLD:
Safety Recall 00S12: Certain 2000 Model Year F-53 Motorhome Stripped Chassis – Push Rod Brake Retainer Clip Inspection / Installation

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

NOTE: All of the vehicles affected by Safety Recall 00S12 are also affected by Owner Notification Program 00B48. Please complete both programs at the same time. Customers affected by both programs will be notified in one letter.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer VIN list which you will receive in the Ford Dealer Consolidated Communicator (FDCC). Also, correct other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII manual for refund information.

RENTAL CARS

Rental vehicles are approved for this program only if the brake retaining clip needs to be ordered. The purpose of the rental vehicle is to provide transportation until the push rod brake retaining clip is installed.

DEMONSTRATION / DELIVERY HOLD:
Safety Recall 00S12: Certain 2000 Model Year F-53 Motorhome Stripped Chassis – Push Rod Brake Retainer Clip Inspection / Installation

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect for improperly installed or missing brake pedal pushrod retainer.	00S12A	0.3 Hours
Install brake pedal pushrod retainer if improperly installed or missing (includes Inspection)	00S12B	0.3 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
380699-S100	Brake Retaining Clip (Package of 5 Retaining Clips)	1

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

July 2000

00S12
00B48

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect that relates to motor vehicle safety exists in certain 2000 Model Year F-53 motorhome stripped chassis.

Also, in order to maintain long-term customer satisfaction, we would like to take this opportunity to perform a no-charge shift cable inspection and torque check on various steering and suspension fasteners.

What the safety issue is…

The brake pedal to hydraulic booster pushrod retainer pin on a small number of the affected vehicles may not have been properly installed on the service brake pedal. Improperly installed or missing retainers could result in loss of service braking capability. This could occur without warning and result in an accident. The vehicle parking brake system is not affected and remains operational.

What the Customer Satisfaction issue is…

The purpose of this no-cost program is to inspect the shift cable to make sure it is fully seated into the cable bracket and verify the torque on the following fasteners:

- Steering Column Yoke Coupling Shaft Retaining Bolt
- Shift Lever Bracket Bolts
- Wheel Lug Nuts
- Steering Gear Mounting Bolts

What Ford Motor Company and your dealer will do...	Ford Motor Company will repair your vehicle free of charge (parts and labor). Your Ford dealer will inspect the Push Rod Brake Retainer clip to make sure it is properly seated. If the retainer clip is missing the dealership will install a new brake retainer clip. In addition, the shift cable will be inspected and a torque check will be performed on all of the fasteners previously listed.
How long will it take?	The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.
What we are asking you to do…	Call your dealer without delay. Ask for a service date for Safety Recall 00S12 and Owner Notification Program 00B48. If inspection reveals that a new retainer clip is required, your dealer may need to order it. Parts would be expected to arrive within a week after ordering. In this event, Ford Motor Company has authorized your dealer to provide a rental car that you may use for transportation. Ford Motor Company will pay for the rental car, except the cost of fuel which will be at your expense. When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.
If you've already paid for this service…	If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.
If you've changed address or sold the vehicle…	Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 1-202-366-0123).

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs