• **DRIVEABILITY—PERCEIVED COLD ENGINE LONG CRANK/HARD START—DIAGNOSTIC TROUBLE CODE (DTC) P1443 STORED IN MEMORY—VEHICLES EQUIPPED WITH 3.0L 24-VALVE ENGINE ONLY BUILT PRIOR TO 10/5/2000** • **ELECTRICAL—LAMP—DIAGNOSTIC TROUBLE CODE (DTC) P1443 STORED IN MEMORY—VEHICLES EQUIPPED WITH 3.0L 24-VALVE ENGINE ONLY BUILT PRIOR TO 10/5/2000** • **TRANSMISSION—SHUDDER/VIBRATION ON DECELERATION IN FIRST GEAR—HARSH COASTING DOWNSHIFTS—DIAGNOSTIC TROUBLE CODE (DTC) P1443 STORED IN MEMORY—VEHICLES EQUIPPED WITH 3.0L 24-VALVE ENGINE ONLY BUILT PRIOR TO 10/5/2000**	**Article No. 01-19-1**

FORD: 2000-2001 TAURUS

MERCURY: 2000-2001 SABLE

ISSUE

Some vehicles built prior to 10/5/2000 equipped with the 3.0L 24-valve Duratec engine, may exhibit:

- Perceived cold engine long crank/hard start
- Transmission shudder/vibration during deceleration, in manual first gear
- Harsh coasting transmission downshifts (2000 Model Year only)
- Erroneous code P1443 stored in memory (2000 Model Year only)

This may be caused by the calibration of the Powertrain Control Module (PCM).

ACTION

If condition is verified, reprogram the PCM. If after PCM reprogramming the condition still exists, continue with normal Workshop Manual diagnosis. Refer to following Service Information and PCM Calibration chart for details.

SERVICE INFORMATION

NOTE

THIS UPDATE MAY IMPROVE COLD ENGINE LONG CRANK TIMES, HOWEVER CUSTOMERS SHOULD BE ADVISED THAT IT IS NORMAL FOR THE VEHICLE TO HAVE A LONGER CRANK TIME COLD VERSUS A HOT ENGINE RESTART. ADDITIONALLY, THE IGNITION SWITCH SHOULD BE HELD FIRMLY IN THE CRANK POSITION UNTIL THE VEHICLE STARTS. IF THE SWITCH IS RELEASED PREMATURELY, BEFORE THE ENGINE STARTS, IT MAY BE NECESSARY TO CYCLE THE SWITCH TO THE OFF POSITION BEFORE THE NEXT CRANKING ATTEMPT. FOR OPTIMUM COLD STARTS 87 OCTANE FUEL SHOULD BE RECOMMENDED.

NOTE

IF USING A NEW GENERATION STAR (NGS) TESTER TO REPROGRAM THE PCM, THE NGS MAY ASK "WOULD YOU LIKE TO MODIFY ANY PCM PARAMETERS?" ANSWER "NO" TO THIS QUESTION. THIS WILL PREVENT CHANGES TO THE TIRE SIZE AND AXLE RATIO. IF "YES" WAS INADVERTENTLY SELECTED, IT MAY BE NECESSARY TO ENTER 797 FOR TIRE SIZE AND 3.47 FOR THE FINAL DRIVE AXLE RATIO.

1. Reprogram the PCM to the latest calibration. Refer to the following PCM Calibration Information Chart for applications.
2. Advise the customer that it may take several drive cycles (dependent on cycle) before the PCM will completely adapt to the new calibration.

Copyright © 2001 Ford Motor Company

Article No. 01-19-1 Cont'd.

PCM CALIBRATION INFORMATION						
Application	**Old Part Number (-12A650-)**	**Old Tear Tag**	**New Part Number (-12A650-)**	**New Tear Tag**	**Old Calibration**	**NGS/WDS Qualifier**
2000 Federal CAA	YF1F-MB	GCM1	YU2Z-ASC	PRZ2	0DD14N0A05	WDS B14.14 Release or Later
2000 Federal CAA	YF1F-MC	GCM2	YU2Z-ASC	PRZ2	0DD14N0A06	WDS B14.14 Release or Later
2000 Federal CAA	YU2F-ASA	PRZ0	YU2Z-ASC	PRZ2	0DD14N0A06	WDS B14.14 Release or Later
2000 Federal CAA	YU2F-ASB	PRZ1	YU2Z-ASC	PRZ2	0DD14N0A06	WDS B14.14 Release or Later
2000 California LEV	YF1F-NB	HUK1	YU2Z-AVC	KDB2	0DD14N0B05	WDS B14.14 Release or Later
2000 California LEV	YF1F-NC	HUK2	YU2Z-AVC	KDB2	0DD14N0B05	WDS B14.14 Release or Later
2000 California LEV	YU2F-AVA	KDB0	YU2Z-AVC	KDB2	0DD14N0B05	WDS B14.14 Release or Later
2000 California LEV	YU2F-AVB	KDB1	YU2Z-AVC	KDB2	0DD14N0B06	WDS B14.14 Release or Later
2000 Federal CAA	YF1F-ADA	ALP0	YU7Z-AAB	DZD1	0DD15N0A00	WDS B14.14 Release or Later
2000 Federal CAA	YF1F-ADB	ALP1	YU7Z-AAB	DZD1	0DD15N0A05	WDS B14.14 Release or Later
2000 Federal CAA	YU7A-AAA	DZD0	YU7Z-AAB	DZD1	0DD15N0A05	WDS B14.14 Release or Later
2000 California LEV	YF1F-AEB	DNV1	YU7Z-ABB	MGN1	0DD15N0505	WDS B14.14 Release or Later
2000 California LEV	YF1F-AEC	DNV2	YU7Z-ABB	MGN1	0DD15N0506	WDS B14.14 Release or Later
2000 California LEV	YU7A-ABA	MGN0	YU7Z-ABB	MGN1	0DD15N0506	WDS B14.14 Release or Later
2001 Taurus/Sable	1F1F-GD	JQP3	1F1Z-GE	JQP4	1DD14N0507	WDS B14.14 Release or Later
2001 Taurus/Sable	1F1F-VC	PAS2	1F1Z-VD	PAS3	1DD14N0G06	WDS B14.14 Release or Later
2001 Taurus/Sable	1F1F-XC	XVH2	1F1Z-XD	XVH3	1DD14N0K06	WDS B14.14 Release or Later

Obtain an Authorized Modifications Decal (STAT 5941-2 - obtainable through the PDC) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) Per TSB 01-19-1
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.
DEALER NUMBER: DATE:
CHANGE AUTHORITY:
FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 206000, 404000, 499000, 502000, 504000, 602300, 603300, 607000, 607400, 610000, 610700, 612000, 613700, 690000, 698298