| ENGINE MOUNTS—REVISED ENGINE MOUNTS FOR SEVERE DUTY VEHICLES | Article No. 01-1-1 |
|---|---|

**FORD:** 1998-2000 CROWN VICTORIA

**LINCOLN:** 1998-2000 TOWN CAR

**MERCURY:** 1998-2000 GRAND MARQUIS

This article is being republished in its entirety to update the model year coverage and part numbers.

## ISSUE

The engine mounts on some vehicles may not exhibit satisfactory durability under severe operating conditions that may be encountered by Police, Taxi or Limo/Livery vehicles such as extended idling at high ambient temperatures. This may be caused by the extreme heat generated by the engine under these conditions.

## ACTION

If service to the engine mounts is required, install new revised engine mounts which incorporate a heat shield. For left side engine mount, use 1W7Z-6038-BA - right side engine mount, use 1W7Z-6038-AA. Refer to the appropriate model/year Workshop Manual, Section 303-01 for replacement procedure.

| PART NUMBER | PART NAME |
|---|---|
| 1W7Z-6038-BA | Engine Mount (Left) |
| 1W7Z-6038-AA | Engine Mount (Right) |

**OTHER APPLICABLE ARTICLES:** NONE
**SUPERSEDES:** 00-21-4
**WARRANTY STATUS:** INFORMATION ONLY
**OASIS CODES:** 497000, 499000, 702000, 702100

Copyright © 2001 Ford Motor Company