LAMP—LICENSE PLATE—LOOSE AND/OR FALLING OUT OF POSITION—VEHICLES BUILT FROM 3/1/1999 THROUGH 5/8/2000	Article No. 00-17-3

LINCOLN: 2000 LS

ISSUE

The rear license plate lamp retention clips may break and the lamp may come loose from the rear license plate chrome housing on some vehicles.

ACTION

Replace both license plate lamp assemblies with revised assemblies. Both lamp assemblies should be replaced with the revised assemblies even if only one lamp comes loose. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Open the trunk.

NOTE

USE CARE TO AVOID KINKING OR DAMAGING THE SECONDARY, INSIDE TRUNK RELEASE CABLE WHEN REMOVING THE LINER.

2. Remove the push pins that secure the truck lid liner and remove the liner.
3. Remove the bulbs from the lamp housings.
4. Release the clips that secure the lamps to the chrome housing.
5. Install the new lamp housings.
6. Reinstall the bulbs.
7. Reinstall the trunk lid liner, taking care to route the secondary trunk release cable correctly.
8. Verify operation of the lamps.

PART NUMBER	PART NAME
1W4Z-13550-AA	License Plate Assembly (2 Req'd.)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
001703A	Replace Both License Plate Lamp Assemblies	0.3 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
13550	01

OASIS CODES: 108000, 201000, 201200

Copyright © 2000 Ford Motor Company