• SUSPENSION—VIBRATION FELT AT SPEEDS ABOVE 72 KM/H (45 MPH) • VIBRATION—VIBRATION FELT AT SPEEDS ABOVE 72 KM/H (45 MPH)	Article No. 00-21-10

FORD: 1999-2000 WINDSTAR

ISSUE

Some vehicles may exhibit a vibration condition at 72 km/h (45 mph) and above. This condition may be noticed after replacing, rotating, or servicing wheel and tire assemblies.

ACTION

Replace the chassis components with parts supplied in Chassis Service Kit 1F2Z-3C304-AA. Refer to the following Service Procedure for details.

NOTE

ALL CHASSIS COMPONENTS IN THE SERVICE KIT MUST BE INSTALLED (NOT PARTIALLY) OR RIDE AND HANDLING OF THE VEHICLE MAY BE AFFECTED.

Components included in Chassis Service Kit 1F2Z-3C304-AA include: Both lower control arms, strut isolators, upper and lower subframe mounts, all necessary hardware for installation, and an instruction sheet. (A #3 engine mount is also included for use with 3.8L engines only.)

SERVICE PROCEDURE

1. Verify vibration over 72 km/h (45 mph).
2. Follow normal Workshop Manual noise, vibration and harshness repair techniques. Refer to the appropriate Windstar Workshop Manual, Section 100-04.
3. If vibration cannot be corrected with normal service procedures, install Chassis Service Kit 1F2Z-3C304-AA.
4. Follow removal and installation procedures in the Workshop Manual as outlined by the instruction sheet included with the kit.
5. Torque new subframe bolts to 115 N•m (85 lb-ft).
6. Check alignment and adjust as necessary.

PART NUMBER	PART NAME
1F2Z-3C304-AA	Chassis Service Kit

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
002110A	Install Chassis Component Kit (3.8L)	4.6 Hrs.
002110B	Install Chassis Component Kit (3.0L)	4.5 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
3051	42

OASIS CODES: 303000, 304000, 703000, 703300

Copyright © 2000 Ford Motor Company