STEERING—POWER STEERING FLUID LEAK DURING EXTREME COLD AMBIENT TEMPERATURES -20 TO -28C (-5 TO -20F)—VEHICLES PRODUCED BEFORE 2/12/2002 ONLY

Article No. 02-5-2

FORD: 2001-2002 ESCAPE

ISSUE

Some vehicles built before 2/12/2002 may exhibit a power steering fluid leak at the Return Hose and/or Cooler Hose at the Intermediate Tube Assembly during extreme cold ambient temperatures -20 to -28°C (-5 to -20 °F). This may be caused by hose blow out due to an increase in fluid viscosity during extreme cold temperatures.

ACTION

Replace the Intermediate Tube with a steel intermediate tube and replace spring type clamps on Return Hose and Cooler Hose with worm type clamps to increase hose retention.

SERVICE PROCEDURE

1. Perform procedure in Workshop Manual Section 211-02 to remove Return Hose and Cooler Hose from Intermediate Tube.
2. Replace Intermediate Tube with new part 2L8Z-3A713-AA.
3. Reinstall Cooler and Return Hoses using worm clamps 376240-S100.
4. Bleed all of the air from steering system using bleed procedure in Section 211-00 of the appropriate year Workshop Manual.

PART NUMBER	PART NAME
2L8Z-3A713-AA	Intermediate Tube - Power Steering
376240-S100	Clamp - Worm Style

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
020502A	Replace Metal Section Of Power Steering Return Hose (Includes Time To Bleed Air From System)	1.0 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
3A713	42

OASIS CODES: 303000

Copyright © 2002 Ford Motor Company