• **BRAKES—"POPPING" NOISE FROM THE BRAKE PEDAL AREA, WITH POSSIBLY PEDAL MOVEMENT—VEHICLES WITH ADVANCE TRAC VEHICLE STABILITY CONTROL SYSTEM BUILT THROUGH 10/11/1999** • **NOISE—"POPPING" FROM THE BRAKE PEDAL AREA—VEHICLES WITH ADVANCE TRAC VEHICLE STABILITY CONTROL SYSTEM BUILT THROUGH 10/11/1999**	**Article No. 99-26-8**

LINCOLN: 2000 LS

This article only applies to vehicles equipped with Advance Trac vehicle stability control system. Vehicles equipped with Advance Trac can be identified by the letters ATS on the traction assist cancel switch located on the center console.

ISSUE

An intermittent "popping" noise coming from the brake pedal area under normal driving conditions, with possibly movement of the brake pedal, may occur on some vehicles. This may be due to a strategy concern within the Electronic Control Unit (ECU) of the Anti-lock Brake System (ABS) and Advance Trac System.

ACTION

Replace the Anti-lock Brake/Advance Trac ECU with the revised ECU. Refer to the following Service Procedure for details.

VERIFICATION

The concern can be verified by the following method:

1. Turn vehicle Off.
2. Start vehicle and let it idle for 8 to 15 minutes.
3. Drive vehicle at speeds greater than 50 km/h (30 mph), foot off the brake, in a smooth and steady manner. During this drive, the popping noise should begin to occur.

SERVICE PROCEDURE

WARNING

BEFORE THE ECU IS REMOVED FROM THE VEHICLE, IT IS NECESSARY TO UPLOAD THE MODULE CONFIGURATION INFORMATION TO THE NEW GENERATION STAR (NGS) TESTER. FOR ADDITIONAL INFORMATION, REFER TO THE 2000 LS WORKSHOP MANUAL, SECTION 418-01.

1. Disconnect the battery ground cable from the battery.
2. Disconnect the anti-lock brake ECU electrical connector by lifting up on the release tab.
3. Remove the two (2) screws that secure the electrical Auxiliary Junction Box (AJB) and position the AJB aside.
4. Remove the four (4) screws that secure the ECU to the Hydraulic Control Unit (HCU) and remove the ECU.

NOTE

THESE SCREWS ARE TORX HEAD FASTENERS. THE SIZE IS AN 'E5' INVERTED TORX. DO NOT ATTEMPT TO USE A CONVENTIONAL SOCKET TO REMOVE THESE FASTENERS. CONVENTIONAL SOCKETS WILL STRIP THE SCREW HEADS.

5. Install the revised ECU. Tighten the four (4) screws that secure the ECU to the HCU to 2 N•m (18 lb-in).
6. Reinstall the AJB.
7. Connect the ECU electrical connector.
8. Reinstall the battery ground cable.
9. Download the module configuration data from the NGS Tester into the ECU. Refer to the Workshop Manual, Section 418-01, for additional information.

Article No. 99-26-8 Cont'd.

NOTE

WHEN THE BATTERY HAS BEEN DISCONNECTED AND RECONNECTED, SOME ABNORMAL DRIVE SYMPTOMS MAY OCCUR WHILE THE VEHICLE RELEARNS ITS ADAPTIVE STRATEGY. THE VEHICLE MAY NEED TO BE DRIVEN 16 KM (10 MILES) OR MORE TO RELEARN THE STRATEGY.

PART NUMBER	PART NAME
YW4Z-2C219-DA	Electronic Control Unit

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
992608A	Replace Electronic Control Unit (ECU)	0.5 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
2C219	42

OASIS CODES: 301000, 702000, 702100, 702300