- **AXLE—FRONT AXLE LEAKS FLUID FROM VENT TUBE—VEHICLES EQUIPPED WITH 4X4 OR AWD**
- **LEAK—AXLE—FRONT AXLE LEAKS FLUID FROM VENT TUBE—VEHICLES EQUIPPED WITH 4X4 OR AWD**

Article No. 02-4-2

FORD: 1995-2001 EXPLORER
1997-2002 RANGER
2001-2002 EXPLORER SPORT TRAC, EXPLORER SPORT

MERCURY: 1997-2001 MOUNTAINEER

This TSB article is being republished in its entirety to update the model applications and model years.

ISSUE

Fluid may leak out of the front axle vent tube on some Explorer/Mountaineer, Ranger and Explorer Sport and Sport Trac vehicles. This may be caused by fluid being thrown toward the axle vent by the gears during vehicle operation.

ACTION

Replace the axle cover and install the Axle Cover Kit (F6TZ-4033-BA). The revised housing cover has a baffle built in to reduce the possibility of fluid being thrown out of the vent during vehicle operation. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Refer to the Instruction Sheet included in the kit and the following text for details.
The Cover Kit (F6TZ-4033-BA) includes the following:

- One (1) Cover
- One (1) Hose
- One (1) Hose Connector
- One (1) Vent Plug
- One (1) Clip
- One (1) Sealant
- One (1) Instruction Sheet

NOTE
SINCE TORQUE PREVAILING FASTENERS MUST NOT BE REUSED, ALL LISTED NUTS AND BOLTS MUST BE ORDERED AND BE ON-HAND FOR EACH AXLE KIT INSTALLED.

PART NUMBER	PART NAME
F6TZ-4033-BA	Cover Kit
N808403-S426	Axle Bolt And Washer
N811242-S426	Pinion Bolt And Washer
N811623-S426	Nut And Retainer
N808985-S100	Wheel End Nut And Washer
F7AZ-19554-CA	Silicone Sealant
XY-75W90-TQL	SAE 75W-90 Premium 4X4 Front Axle Lubricant

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 01-8-6
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
020402A	Install Axle Cover Kit	1.7 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
4022	D1

OASIS CODES: 509000, 510000

Copyright © 2002 Ford Motor Company