| | |
|---|---|
| • **DRIVEABILITY—ROUGH IDLE—DIAGNOSTIC TROUBLE CODES (DTCS) P0500, P0501, P0503, P1721, P0176, OR P1000 STORED IN MEMORY—WATER INTRUSION AT CONNECTOR C309 OR C340 UNDER DRIVER'S SEAT—VEHICLES PRODUCED BEFORE 1/2/2001**<br>• **ELECTRICAL—ANTI-LOCK BRAKE (ABS) LAMP ILLUMINATED—DIAGNOSTIC TROUBLE CODE (DTC) C1230 OR CODES 9 OR 16 STORED IN MEMORY—WATER INTRUSION AT CONNECTOR C309 OR C340 UNDER DRIVER'S SEAT—VEHICLES PRODUCED BEFORE 1/2/2001**<br>• **ELECTRICAL—SPEEDOMETER—INOPERATIVE OR ERRATIC OPERATION—WATER INTRUSION AT CONNECTOR C309 OR C340 UNDER DRIVER'S SEAT—VEHICLES PRODUCED BEFORE 1/2/2001**<br>• **TRANSMISSION—4R44E—ROUGH/HARSH OR DELAYED UPSHIFT—WATER INTRUSION AT CONNECTOR C309 OR C340 UNDER DRIVER'S SEAT—VEHICLES PRODUCED BEFORE 1/2/2001** | **Article No. 01-5-2** |

**FORD:** 2000-2001 RANGER

## ISSUE

Some vehicles may exhibit a rough idle, Anti-lock Brake System (ABS) warning lamp illumination, inoperative or erratic speedometer, Diagnostic Trouble Codes (DTCs) P0500, P0501, P0503, P1721, P0176, P1000, ABS DTC 9, RABS DTC 16, or a delayed or harsh shifting automatic transmission. This may be caused by water intrusion at connector C309 (2000 model year) or C340 (2001 model year) under the driver's seat.

## ACTION

Inspect affected connectors; clean or replace connector pins as necessary. Install new sleeve and boot assembly over -14401- connector (interior). Refer to the following Service Procedure for details.

## SERVICE PROCEDURE

Verify water intrusion in connector C309 for 2000 model year or C340 for 2001 model year applications by removing bottom half (male) connector located on -14405- wire harness assembly under driver's seat, outside, beneath vehicle's cab. If water is present or pins are damaged, remove connector sleeve and perform the following:

### INSIDE CAB

- Remove driver's seat
- Remove driver's door scuff plate
- Peel carpet or vinyl lining back to gain access to top portion of connector C309F (for 2000 model year) or C340F (for 2001 model year)

Copyright © 2001 Ford Motor Company

**F = Female Side Of Connector**

- Remove connector from floor pan by depressing locking tabs on side of connector
- Remove cap from back of connector to gain access to the pins
- Remove red locking wedge from face of connector
- Remove each pin individually and clean accordingly

**NOTE**
**IF PINS ARE DAMAGED BEYOND THE ABILITY TO CLEAN, OBTAIN NEW PINS FOR REPAIR. ALL PINS WILL REQUIRE SOLDERING TO WIRE FOR MORE ROBUST CONNECTION. REFERENCE APPROPRIATE PINS:**

F67Z-14487-AA replacing silver finish pins (1.6mm) and/or E6DZ-14487-AA replacing gold/brass finish pins (1.6mm) and/or F6DZ-14487-BA replacing gold/brass finish pins (2.8mm).

- When all pins are cleaned or replaced, install new Cap (1L5Z-14A541-AA) over existing connector 14A464
- Insert all pins through new Rubber Boot (1L5Z-14A099-AA)
- Install pins into existing connector (refer to the appropriate Electrical and Vacuum Troubleshooting Manual (EVTM) for correct pin positions)
- Install existing red locking wedge and seat rubber boot to new cap
- Insert connector into sheet metal (floor pan area)

**OUTSIDE CAB UNDERNEATH VEHICLE/DRIVER'S SIDE**

- Remove cap from back of connector C309M (2000 model year) or C340M (2001 model year)

**M = Male Side Of Connector**

- Remove white locking wedge from face of connector
- Remove each pin individually, clean accordingly, and re-insert into correct cavity of lower connector 14A624 (refer to EVTM for correct pin position)

**NOTE**
**IF PINS ARE DAMAGED BEYOND THE ABILITY TO CLEAN, OBTAIN NEW PINS FOR REPAIR. ALL PINS WILL REQUIRE SOLDERING TO WIRE FOR MORE ROBUST CONNECTION. REFERENCE APPROPRIATE PINS:**

E7EB-14461-BA replacing silver finish pins (1.6mm) and/or F6TZ-14461-AA replacing gold/brass finish pins (1.6mm) and/or F6DZ-14461-CA replacing silver finish pins (2.8mm) and/or E5DZ-14461-A replacing silver finish (1.6mm Circuits 52 and 64)

- Install existing white locking wedge and reseat existing cap to back of connector C309M (2000 model year) or C340M (2001 model year)
- Apply dielectric grease sparingly to all pins
- Slide sleeve over upper connector and lock-in place
- Slide lower connector over sleeve and secure with bolt in connector - torque bolt to 4.8 ±0.8 N•m (42.5 ±7 lb-in)

After connector has been reinstalled, verify concern has been eliminated. Reinstall carpet or vinyl lining, door scuff plate, and driver's seat.

| PART NUMBER | PART NAME |
|---|---|
| 1L5Z-14A099-AA | Rubber Connector Boot |
| 1L5Z-14A541-AA | Plastic Connector Cap |
| F67Z-14487-AA | Female Side - Silver Finish Pins (1.6mm) |
| E6DZ-14487-AA | Female Side - Gold/Brass Finish Pins (1.6mm) |
| F6DZ-14487-BA | Female Side - Gold/Brass Finish Pins (2.8mm) |
| E7EB-14461-BA | Male Side - Silver Finish Pins (1.6mm) |
| F6TZ-14461-AA | Male Side - Gold/Brass Finish Pins (1.6mm) |
| F6DZ-14461-CA | Male Side - Silver Finish Pins (2.8mm) |
| E5DZ-14461-A | Male Side - Silver Finish (1.6mm Circuits 52 And 64) |

**OTHER APPLICABLE ARTICLES:** NONE

**WARRANTY STATUS:** Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

| OPERATION | DESCRIPTION | TIME |
|---|---|---|
| 010502A | Perform Wire Connector Update (Includes Time To Clean Or Replace Wire Terminals As Required) | 4.3 Hrs. |

**DEALER CODING**

| BASIC PART NO. | CONDITION CODE |
|---|---|
| 14401 | X2 |

**OASIS CODES:** 201200, 203000, 204000, 206000, 301000, 404000, 508000, 602300, 608000, 610000, 611000, 698298