Related Newsletter Articles

01B78 Supplement II – Instrument Panel Warpage

08/12/2002

"U" Clips for defroster opening:
The "U" clips that are included to be installed around the defroster opening are OPTIONAL since they are not required to complete the installation of the defroster cover. If the "U" clips can't be installed with little or no removal of substrate material, do not install them. The defroster cover has sufficient retention capability to hold the vinyl in-place and make a durable repair.

Removal of the IP to complete the Repair:
It is not necessary to remove the IP to complete this repair. The time for completing the repair (01B78G) does not include the removal of the IP and does not justify additional time for the repair. The instrument panel will move rearward far enough to allow sufficient access for installation of the molding at the forward edge of the IP as well as drilling the rivet holes for the defroster grille and defroster grille cover.

01B78 Supplement II – Helpful Tip for Instrument Panel Repairs

07/08/2002

If installation of the retention U-clips to hold the instrument panel skin down along the rear defroster edge is not possible due to the amount of shrinkage or delamination present, it is permissible to utilize other mechanical means such as riveting the skin in an area that will still be covered by the defroster cover as temporary retention until defroster cover installation. It is also permissible to utilize the extra rivets that come with the kit for this procedure.

01B78 Supplement II - Instrument Panel Replacement Exceptions

07/01/2002

Instrument panels with extreme warpage have been successfully repaired by the new repair kit ("DA" kit). For this reason, IP replacement is no longer needed for this program. However, there may be cases where deviations are granted. Please refer to the 01B78 Supplement #2 document for details. Replacement deviations will not be granted for any cases, regardless of approvals, that have not had the new "DA" kit installed. IP's that have cosmetic concerns are not replaceable under this program. Replacement IP's will only be approved when a claim for 01B78G, for repair kit installation is in the warranty system.

The repair kit (1S2Z-5404282-DA), will be available for order through normal channels effective Monday June 24, 2002.

Contact dealerships should only be contacting their Field Service Engineers and Select dealerships should only be contacting the Special Service Support Center for instrument panel replacement after the "DA" kit has been installed unsuccessfully. Regional personnel will be unable to assist dealers that do not meet these criteria. Visual inspection of a delaminated IP is not sufficient to qualify for instrument panel replacement.

01B78 Instrument Panel Warpage

05/27/2002

01B78 will be temporarily suspended on May 28, 2002 and will be reinstated the week of June 10, 2002 to allow sufficient time to procure enough parts to allow the launch of the new repair. Instrument panel replacement is no longer part of the repair for this program due to the effectiveness of the new repair. Please note that claims with the labor operation for the supplement #1 repair (01B78F) with a repair date after the week of June 10, 2002 will not be accepted for payment. In addition, claims with a repair date later than May 28, 2002, for instrument panel replacement (01B78C and 01B78E) will not be accepted. Only one labor operation is allowable per repair order (claim) for this program.

Please note: This program only addresses delamination of the instrument panel's vinyl skin. Damage, discoloration, bubbles or foam voids are not covered under this program.

Copyright © 2002 Ford Motor Company
Published By: **Recall & Service Programs Department**
Ford Customer Service Division