TRANSMISSION—4R70W—OVERDRIVE INOPERATIVE—VEHICLES PRODUCED 3/26/2002 THROUGH 6/30/2002 EQUIPPED WITH POLICE PACKAGE ONLY

Article No. 02-24-2

FORD: 2003 CROWN VICTORIA

ISSUE

Some police package equipped Crown Victoria vehicles produced 3/26/2002 through 6/30/2002, may exhibit a loss of 4th gear (overdrive). This may be caused by forced 4-2 downshifts (usually from high speeds). The original PCM (Powertrain Control Module) calibration may allow transmission component engagements during forced 4-2 downshifts in a manner that may lead to failure of the Overdrive Band.

ACTION

Verify the condition. Diagnose and repair Transmission per the Workshop Manual. Verify that the PCM calibration is at the latest level, if not, it must be reprogrammed. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Follow the normal diagnostic procedures to verify no 4th gear operation.
2. Replace the OD band F2TZ-7F196-A if no 4th gear or slipping 4th gear. Follow all the normal procedures as shown in the Workshop Manual.
3. Use the procedures found in the Powertrain Control/Emissions Diagnosis (PC/ED) Workshop Manual and reprogram the PCM. Refer to the following PCM Calibration Information Chart.
4. Clear all Diagnostic Trouble Codes (DTC)s and validate service. If the condition is not corrected, continue with Diagnosis By Symptom as shown in the Workshop Manual.

PCM CALIBRATION INFORMATION

Application	Old Part Number (-12A650-)	Old Tear Tag	New Part Number (-12A650-)	New Tear Tag	Old Calibration	New Calibration	NGS/WDS Qualifier
2003 Crown Victoria with Police Package	3W7A-BFA	FIT1	3W7Z-BFB	FIT2	3FB1AP0510	3FB1AP0510	WDS B22NM_2 Release or Later
2003 Crown Victoria Police Long Wheel Base	3W7A-BGA	GHC1	3W7Z-BGB	GHC2	3FB1AL0510	3FB1AL0510	WDS B22NM_2 Release or Later

Obtain an Authorized Modifications Decal (FPS 8262 - obtainable through DOES II, 25/pkg) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by “do-it-yourselfers”. Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) Per TSB 02-24-2
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.

DEALER NUMBER: **DATE:**

CHANGE AUTHORITY:

FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

PART NUMBER	PART NAME
F2TZ-7F196-A	Band - Transmission Overdrive

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 501000, 504000