- **NOISE—GEAR WHINE NOISE IN 1ST AND 2ND GEAR ONLY—VEHICLES EQUIPPED WITH 5R55E TRANSMISSION AND 4.0L ENGINE ONLY**
- **TRANSMISSION—5R55E—GEAR WHINE NOISE IN 1ST AND 2ND GEAR ONLY—VEHICLES EQUIPPED WITH 4.0L ENGINE ONLY**

Article No. 02-22-2

FORD: 2001-2003 EXPLORER SPORT TRAC, EXPLORER SPORT, RANGER

ISSUE

Some 2001-2003 Rangers, 2001-2003 Explorer Sport/Sport Trac, built prior to 10/18/2002, equipped with a 5R55E automatic transmission and 4.0L engine, may exhibit a gear whine type of noise in 1st and 2nd gear ONLY. This may be caused by the Reverse and Forward Planetary assemblies and/or the driveshaft.

ACTION

Verify that only these conditions exist and no DTCs are present. If other conditions are present and DTCs exist they must be diagnosed and serviced first. Once all other conditions are serviced and only the 1st and 2nd gear whine are still present, refer to the following Service Procedure. Using the chart provided, select the parts that need to be replaced.

NOTE
IF PLANETARIES ARE LISTED, BOTH MUST BE REPLACED.

SERVICE PROCEDURE

Gear Whine Service Procedure

1. Determine whether the driveshaft only, planetaries only or both driveshaft and planetaries need to be replaced, refer to Application and Component replacement chart.
2. If just the driveshaft needs to be replaced follow the procedures as listed in the appropriate Workshop Manual section for driveshaft removal/replacement.
3. If the planetaries need to be replaced, using the appropriate model and year Workshop Manual, Section 307-01, Transmission Removal procedures, remove the transmission.
4. Discard the driveshaft ONLY if being replaced. Refer to application and component replacement chart.

NOTE
REPLACEMENT OF THE EXTENSION HOUSING SEAL AND BUSHING ARE NOT REQUIRED. DO NOT DISASSEMBLE BEYOND THE REVERSE PLANETARY. ALL SUBASSEMBLY STEPS ARE NOT REQUIRED FOR THIS PROCEDURE.

NOTE
BOTH PLANETARIES MUST BE REPLACED OR THE REPAIR MAY NOT BE EFFECTIVE.

5. Using the Transmission Disassembly procedures remove the Forward Planetary Assembly (7A398) and the Reverse Planetary Assembly (7D006) and discard. Do not disassemble beyond the Reverse Planetary assembly.
6. Using the appropriate Transmission Assembly procedures, assemble the transmission and install BOTH NEW service Reverse Planetary Assembly (XL2Z-7D006-AA) and a new service Forward Planetary Assembly (XL2Z-7A398-AA).
7. Using the appropriate model and year Workshop Manual, Section 307-01, Transmission Installation procedures, install transmission.
8. If being replaced, Install the NEW service driveshaft 2L2Z-4602-AA as required for the appropriate application listed.
9. Verify repair. Clear DTCs.

Copyright © 2002 Ford Motor Company

Application And Component Replacement Chart	
Application	**Replacement Components Needed**
2001-2003 Ranger	Forward and Reverse Planetaries and NO Driveshaft
2001-2002 Explorer Sport built prior to 8/12/02	Forward and Reverse Planetaries Only and NO Driveshaft
2001-2002 Explorer Sport Trac 4x4 built prior to 8/12/02	Forward and Reverse Planetaries Only and NO Driveshaft
2001-2002 Explorer Sport Trac 4x2 built prior to 8/12/02	Forward and Reverse Planetaries and Driveshaft
2002 -2003 Explorer Sport Trac 4x2, built 8/12/02 thru 10/18/02	Driveshaft Only

PART NUMBER	PART NAME
XL2Z-7D006-AA	Reverse Planetary Assembly
XL2Z-7A398-AA	Forward Planetary Assembly
2L2Z-4602-AA	Driveshaft

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
022202A	Replace Transmission Forward And Reverse Planetary Assemblies (Includes Time To Remove And Install Transmission 5R55E) 2001-2003 Explorer Sport/Sport Trac And Ranger 4.0L 4X2	5.5 Hrs.
022202B	Replace Transmission Forward And Reverse Planetary Assemblies (Includes Time To Remove And Install Transmission 5R55E) 2001-2003 Explorer Sport/Sport Trac And Ranger 4.0L 4X4	7.0 Hrs.
022202C	Replace Driveshaft Only 2002-2003 Explorer Sport Trac 4x2	0.4 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
7A398	42

OASIS CODES: 501000, 502000, 504000, 597997, 703200, 703400

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.