• **DRIVEABILITY—TICKING NOISE FROM DASH MOUNTED DELTA PRESSURE FEEDBACK EGR (DPFE) SENSOR AND/OR DIAGNOSTIC TROUBLE CODES (DTC) P0401/0402** • **NOISE—TICKING NOISE FROM DASH MOUNTED DELTA PRESSURE FEEDBACK EGR (DPFE) SENSOR AND/OR DIAGNOSTIC TROUBLE CODES (DTC) P0401/0402**	**Article No. 02-13-1**

FORD: 2001-2002 FOCUS

ISSUE

Some 2001 vehicles equipped with a 2.0L SPI engine may exhibit a pulsing or ticking noise originating from the engine compartment and/or may have a MIL light with DTC P0401 or P0402 code. Some 2002 vehicles built 12/1/2001 through 5/21/2002 equipped with 2.0L Zetec engine and a dash mounted DPFE sensor, may also exhibit a MIL light with DTC P0401 or P0402. This may be caused by the Delta Pressure Feedback EGR (DPFE) sensor.

ACTION

If diagnosis leads to a failed DPFE sensor, order DPFE Service Kit (3S4Z-9P449-AA) and follow the instructions supplied with the kit to install.

PART NUMBER	PART NAME
3S4Z-9P449-AA	DPFE Sensor Service Kit

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emissions Warranty Coverage

OPERATION	DESCRIPTION	TIME
021301A	Replace Dash Mounted Delta Pressure Feedback (DPFE) Sensor And Wiring Connector Following Instructions In Kit	0.6 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
9J460	42

OASIS CODES: 698298, 702000, 702300

Copyright © 2002 Ford Motor Company