TRANSMISSION—5R55S—SHUDDER DURING 4/5 UPSHIFT AND 5/4 DOWNSHIFT OR HARSH 2-3 UPSHIFT DURING THROTTLE BACKOUT—VEHICLES BUILT 2/15/2002 THROUGH 8/19/2002 EQUIPPED WITH 4.6L ENGINE ONLY

Article No. 02-18-5

FORD: 2002 EXPLORER

MERCURY: 2002 MOUNTAINEER

ISSUE

Some vehicles equipped with 4.6L engine and 5R55S automatic transmission built 2/15/2002 through 5/15/2002, may exhibit a shudder during 4/5 upshift and/or 5/4 downshift, or vehicles built between 5/15/2002 through 8/19/2002 may exhibit a harsh 2-3 throttle backout upshift. This may be caused by the Powertrain Control Module (PCM) calibration.

ACTION

Verify the condition and reprogram the PCM. If the condition is not corrected after reprogramming, continue with normal diagnostics to pinpoint the cause. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Verify that one or both of the conditions exists:

1. A shudder exists only during a 4-5 or 5-4 shift and or,
2. A harsh 2-3 upshift occurs only when backout of the throttle.

Prior to performing any service procedures, verify tear tag information. Refer to the PCM Calibration Information Chart in this article. If the calibration is not at the latest level, follow the procedures found in the Powertrain Control/Emissions Diagnosis (PC/ED) Service Manual to reprogram the PCM to latest calibration level.

After reprogramming has been completed, the transmission adaptive strategy for pressure control on engagements must be updated.

Install diagnostic equipment and monitor the Transmission Fluid Temperature (TFT).

Warm the transmission fluid to at least 130° F (54° C as indicated by the TFT.

- Perform five (5) engagements from Park to Reverse. Each engagement must be 5 seconds apart
- Perform five (5) engagements from Drive to Reverse. Each engagement must be 5 seconds apart
- Perform five (5) engagements from Reverse to Drive. Each engagement must be 5 seconds apart
- Perform five (5) engagements from Neutral to Drive. Each engagement must be 5 seconds apart.

NOTE

ALL OF THESE ENGAGEMENTS MUST BE PERFORMED IN ORDER FOR THE ENGAGEMENT PRESSURES TO PROPERLY ADAPT WITH THE NEW CALIBRATION.

Verify repair. If the condition is not corrected, continue with normal diagnostics and repair per the Workshop Manual.

Copyright © 2002 Ford Motor Company

Article No. 02-18-5 Cont'd.

PCM CALIBRATION INFORMATION							
Application	**Old Part Number (-12A650-)**	**Old Tear Tag**	**New Part Number (-12A650-)**	**New Tear Tag**	**Old Calibration**	**New Calibration**	**NGS/WDS Qualifier**
4.6L US And Canada	2L2A-HD	HQK3	2U7Z-CHA	HVX0	2U51A50507	2U51A50510	WDS B20.8 Release or Later
4.6L Mexico	2L2A-PD	FDR3	2U7Z-CJA	JKE0	2U51A50507	2U51A50510	WDS B20.8 Release or Later
4.6L	2L2A-AGD	OXZ3	2U7Z-CKA	KJC0	2U51A50E07	2U51A50E10	WDS B20.8 Release or Later
4.6L	2L2A-AJD	RHD3	2U7Z-CLA	WSJ0	2U51A50J07	2U51A50J10	WDS B20.8 Release or Later
4.6L US And Canada	2L2A-HE	HQK4	2U7Z-CHA	HVX0	2U51A50510	2U51A50510	WDS B20.8 Release or Later
4.6L Mexico	2L2A-PE	FDR4	2U7Z-CJA	JKEO	2U51A50M10	2U51A50M10	WDS B20.8 Release or Later
4.6L	2L2A-AGED	OXZ4	2U7Z-CKA	KJC0	2U51A50E10	2U51A50E10	WDS B20.8 Release or Later
4.6L	2L2A-AJE	RHD4	2U7Z-CLA	WSJ0	2U51A50J10	2U51A50J10	WDS B20.8 Release or Later

Obtain an Authorized Modifications Decal (FPS 8262 - obtainable through DOES II, 25/pkg) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

Ford AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:

Reprogrammed Powertrain Control Module (PCM) Per TSB 02-18-5

THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.

DEALER NUMBER: DATE:

CHANGE AUTHORITY:

FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
021805A	Verify Concern If Present Reprogram The PCM To The Lastest Level. Removal Of PCM To Retrieve Tear Tag Information And Relearning Of Transmission Adaptive Strategy Included.	1.7 Hrs.

DEALER CODING

	CONDITION CODE
BASIC PART NO.	
RECAL	42

OASIS CODES: 501000, 502000

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.