Ford Motor Company

A.R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

August 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 01S25: Certain 1999, 2000 and 2001 Model Year Windstar -- Wiper Motor Gear Cover Replacement

AFFECTED VEHICLES

Certain 1999, 2000 and 2001 model year Windstar built at the Oakville assembly plant from April 16, 1998 through June 2, 2001.

SAFETY CONCERN

In some of the affected vehicles, contaminants such as water, salt, and windshield washer solution may enter the wiper motor cover assembly through pinholes in the exterior of the cover that are used in the molding process. In addition, on certain of the vehicles built between February 2000 and August 2000, a switch located in the plastic cover of the wiper motor gear case may malfunction and overheat.

Either of these conditions may potentially result in loss of intermittent wiper function, smoke or, potentially, ignition of the plastic cover material. Switch malfunction is most likely to occur when the intermittent setting of the wipers is being used, or when snow or ice obstructs the blades from returning to the 'parked' position at the bottom of the windshield.

SERVICE ACTION

On all of the affected vehicles, dealers will install a new wiper motor gear cover assembly that has improved sealing and water resistance.

FORDSTAR BROADCAST

Ford Motor Company will be providing dealers with a special Fordstar Broadcast that explains this repair in detail. The broadcast will air three times per week, once per day, for four weeks, starting on August 16, 2001. Refer to the Campaign Connection Newsletter for specific broadcast times and dates.

© Copyright 2001 Ford Motor Company

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:……...1-800-423-8851
Other (Dealer Only) Recall Questions:……...1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

Safety Recall 01S25
Certain 1999, 2000 and 2001 Model Year Windstar
Wiper Motor Gear Cover Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles in your dealer on-line Involved Unit Listings available on QCDealer.com. Also, correct other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

NOTE: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this field service action is a violation of law in several states/provinces/countries. Accordingly, limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Rental cars are not authorized for this program.

© Copyright 2001 Ford Motor Company

Safety Recall 01S25
Certain 1999, 2000 and 2001 Model Year Windstar
Wiper Motor Gear Cover Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace wiper motor gear cover	01S25B	0.7 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts will be seed stocked for this recall. For details, refer to Safety Recall 01S24, issued on August 9,2001, which uses the same part. Order additional parts requirements through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
1F2Z-17D532-CA	Wiper Motor Gear Cover	1

ORDER INFORMATION

DOR/COR number 50254 identifies parts ordered for this campaign.

DEALER PRICE

For latest prices, refer to DOES II or your updated Price Book.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures”.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2001 Ford Motor Company

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

August 2001

01S25

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 1999, 2000 and 2001 model year Windstar vehicles.

What the safety issue is …

In some of the affected vehicles, contaminants such as water, salt, and windshield washer solution may enter the wiper motor cover assembly through pinholes in the exterior of the cover that are used in the molding process. In addition, on certain of the vehicles built between February 2000 and August 2000, a switch located in the plastic cover of the wiper motor gear case may malfunction and overheat.

Either of these conditions may potentially result in loss of intermittent wiper function, smoke or, potentially, ignition of the plastic cover material. Switch malfunction is most likely to occur when the intermittent setting of the wipers is being used, or when snow or ice obstructs the blades from returning to the 'parked' position at the bottom of the windshield.

What Ford Motor Company and your dealer will do ...

At no charge to you, Ford Motor Company will install a new wiper cover with improved sealing and water resistance.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

© Copyright 2001 Ford Motor Company

What we are asking you to do …

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 01S25. If you do not already have a servicing dealer, you may access www.dealerconnection.com for dealer addresses, maps, and driving instructions.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

Important: Before repairs are made, you may reduce the likelihood of the switch malfunction condition occurring by not using the intermittent function of the wiper system, and by clearing the windshield (during winter months) of packed snow or ice.

If you've already paid for this service …

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle …

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this recall.

If you still have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance. If you still need assistance, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

Call: (866) 436-7332

Office Hours: (Eastern Standard Time)

Monday-Friday:	8am - 11pm
Saturday:	9am - 6pm

Or you may contact us through the Internet at …

Hearing impaired call (800) 232-5952
TDD for the hearing impaired.

www.ownerconnection.com

If you are still having trouble getting your vehicle repaired and without charge, you may write to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.

© Copyright 2001 Ford Motor Company

Quality Care service is there for you all year long.

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company