LAMP—INTERIOR LAMP STAYS ON

Article No. 99-24-8

FORD: 1998-2000 CONTOUR

MERCURY: 1998-2000 MYSTIQUE

ISSUE

The interior lamp may remain on on some vehicles. This may be caused by a short to ground in one of the entry switches and/or the key cylinder illumination switch.

ACTION

Perform Diagnostic Procedure listed below for the appropriate vehicle and repair as required.

DIAGNOSTIC PROCEDURE

1998 CONTOUR/MYSTIQUE

1. Check the following circuits for shorts to ground. The circuits are accessible at the two connector blocks located on top of the central junction box or at the black 10-way connector on the bottom of the central junction block. Unplug the connectors from the central junction block and check the following circuits for continuity to ground.

Connector/ Color	Circuit No./Color	Description
361/Black (10-way)	31S-LC1 Black/Blue	Courtesy light relay (footwell light circuit) ground
367/Black (10-way)	31S-LB3 Black/Blue	Courtesy light relay (dome light circuit) ground
366/Black (10-way)	8-LC5 White/Red	Passenger and rear door entry switches
366/Black (10-way)	8-LC9 White/Black	Driver door entry switch
*366/Black (10-way)	31S-LC3 Black/Blue	Key cylinder illumination entry switches

* The key cylinder illumination switches were deleted on 1998 models, but the circuitry was not deleted.

2. If circuit is grounded, trace circuit to location of short and repair.

3. Check unconnected key cylinder illumination switches, Connectors C512 or C612, located in either front door for signs of water. Disassemble, clean and dry the connectors. Re-assemble and wrap with water resistant tape.

1999-2000 CONTOUR/MYSTIQUE

1. Prior to investigating potential shorts, make sure that the dimmer switch located on the dash is in the off/dimmer position.

2. Check the following circuits for shorts to ground. The circuits are accessible at the two connector blocks located on top of the central junction box or at the black 10-way connector on the bottom of the central junction block. Unplug the connector from the central junction block and check the following circuits for continuity to ground.

Connector/ Color	Circuit No./Color	Description
361/Black (10-way)	31S-LC1 Black/Blue	Courtesy light relay (footwell light circuit) ground
* 367/Black (10-way)	31S-LB3 Black/Blue	Courtesy light relay (dome light circuit) ground
366/Black (10-way)	8-LC5 White/Red	Passenger and rear door entry switches
366/Black (10-way)	8-LC9 White/Black	Driver door entry switch

* Can be Circuit 31S-LB23A Black/White for some late 1999 models and all 2000 models.

3. If circuit is grounded, trace circuit to location of short and repair.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
992408A	For Wire Circuit Diagnostics, Use “A” Time As Outlined In The Warranty And Policy Manual	

DEALER CODING

BASIC PART NO.	CONDITION CODE
14A005	42

OASIS CODES: 201000, 201100