• AIR CONDITIONING—BLOWER MOTOR STAYS ON HIGH—EATC VEHICLES ONLY • AIR CONDITIONING—TEMPERATURE DOES NOT MAINTAIN SETPOINT—EATC VEHICLES ONLY	Article No. 00-11-2

FORD: 2000 CROWN VICTORIA, TAURUS
1999-2000 EXPLORER

LINCOLN: 2000 LS, TOWN CAR

MERCURY: 2000 GRAND MARQUIS, SABLE
1999-2000 MOUNTAINEER

ISSUE

On some vehicles equipped with Electronic Automatic Temperature Control (EATC), there may be concerns where the blower motor may stay on high after desired temperature is reached, where temperature control does not maintain setpoint, and/or where the temperature gradually wanders away from the setpoint.

ACTION

Refer to the following Service Procedure to aid in normal diagnostics of the EATC system.

SERVICE PROCEDURE

If no Diagnostic Trouble Codes (DTCs) are obtained during the EATC/DATC module self-test, refer to the following diagnostic Service Procedure.

1. Inspect the in-car temperature sensor aspirator hose for proper connections at both ends.
2. Inspect the aspirator hose for kinks or cuts.
3. On applicable vehicles, verify that the in-car temperature sensor is attached and firmly seated to the dash panel. Some vehicles mount the sensor on two pins located on the dash panel. The sensor may be mounted onto the pins loosely and not seated firmly against the dash panel, causing a gap in the sensor-to-dash panel seal and allowing warm air from behind the instrument panel to be drawn across the sensor.
4. Explorer/Mountaineer Only: Check the mounting fasteners to verify that the gap in the fastener is facing horizontally (i.e., at 3 or 9 o'clock). If the gap in the fastener is facing vertically (i.e., 6 or 12 o'clock), the sensor will require greater pressure to seat firmly against the instrument panel.

NOTE
A LOOSELY MOUNTED IN-CAR TEMPERATURE SENSOR, OR ASPIRATOR HOSE WITH CUTS OR KINKS MAY CAUSE SYSTEM TO BE UNABLE TO MAINTAIN SETPOINT TEMPERATURE OR SETPOINT IS REACHED BUT SYSTEM GRADUALLY COOLS.

EATC/DATC Aspiration Test

This test will determine if the in-car temperature sensor is receiving enough aspiration. A lack of aspiration may result in an incorrect in-car temperature sensor reading and may cause the EATC/DATC system to act erratically and/or EATC/DATC blowing too cold or too warm.

1. Cut a piece of toilet tissue or tissue paper about 2.5 x 2.5 cm (1″ x 1″).

NOTE
PAPER TOWEL WILL NOT WORK CORRECTLY.

2. Turn key on, fan speed to HIGH BLOWER, and select PANEL or VENT mode.
3. Place the piece of tissue paper over the aspirator grille opening. If aspiration (suction) is present, the tissue paper should stick to the grille.
4. Slowly lower the fan speed to LOW BLOWER. The tissue should continue sticking to the grille.

5. Turn the fan speed to HIGH BLOWER, then to OFF. Tissue paper should fall off the grille.
6. If the tissue paper falls off the aspirator grille when the blower fan is on in any speed:
   a. Verify that the aspirator hose is properly connected at both ends. Check the aspirator hose for kinks or cuts.
   b. Verify that the in-car temperature sensor is properly installed/sealed against the dash panel.
   c. Repair as required.
7. On vehicles equipped with a coolant control valve, check for proper operation of the coolant control valve. Visually inspect vacuum hoses for kinks, leaks, or disconnects.
8. Temperature differentials between panel/floor/defrost vents in mix modes and temperature setpoints that are not at full cool or full heat may exist and are considered normal and not repairable.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 208000, 208100, 208200, 208300, 208999