• TRIM—WHITE FLAKES COMING FROM A/C VENTS • CLIMATE CONTROL—WHITE FLAKES COMING FROM A/C VENTS	Article No. 02-12-1

FORD: 2000-2002 EXPEDITION, F-150

LINCOLN: 2000-2002 NAVIGATOR

Article **01-25-3** is being republished in its entirety to update the model year coverage.

ISSUE

Some vehicles may exhibit white flakes coming from the A/C vents when the blower motor is engaged. This may be caused by excessive amounts of brazing flux utilized in the manufacturing process of the evaporator.

ACTION

Using compressed air (90-150psi), clean the A/C ducts through the registers and blow off the evaporator core through the blower motor opening. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

Vehicle Preparation:

Evaporator core surface must be dry for best results. If unsure, run blower on high for 5 minutes with A/C off. Shut off system, wait 5 minutes, then repeat. Once complete, shut vehicle off and allow to sit for 1 hour.

Service Procedure - Clean A/C Ducts:

1. Remove floor duct trim.
2. Using tape, connect vacuum cleaner to floor duct on driver side in such a way as to collect powder.
3. Tape off other floor duct openings.
4. Connect 2 foot piece of flexible vacuum tubing to compressed air gun using clamp.
5. Close all instrument panel registers.
6. Place temperature setting in full cold.
7. Place mode in floor/panel.
8. Turn on vacuum cleaner.
9. Open one register at a time and blow down through each duct for 30 seconds. Be sure to close each register before moving on to next register.
10. Change mode to floor/defrost.
11. Blow down each defroster duct for 30 seconds.
12. Alternate mode door between floor and floor/defrost 3 times, giving the door time to move between each change.
13. Turn off vacuum cleaner.

Service Procedure - Clean Evaporator Core:

1. Change mode to full floor.
2. Ensure temperature is full cold.
3. Remove blower motor per Workshop Manual.
4. Turn on vacuum cleaner.
5. Reach into blower opening with tubing and proceed to clean core.
6. Blow core for a minimum of 5 minutes, utilizing a very slow sweeping action.
7. Blow the entire core face in the up and down direction, then repeat moving from side to side.
8. Ensure coverage of the entire core.

NOTE

ATTENTION TO THE BLOW-OFF OF THE EVAPORATOR CORE SURFACE WILL DETERMINE EFFECTIVENESS OF REPAIR.

9. Re-assemble the blower motor.
10. Open all registers.
11. Operate the system with A/C on and blower on Max in each mode setting with the temperature full cold and then full warm. Be sure to stay in each mode position for at least 30 seconds to ensure removal of any residual flakes/dust.

Copyright © 2002 Ford Motor Company

12. Disconnect vacuum cleaner and remove tape from floor duct.

13. Re-assemble floor duct trim.

Service Procedure - Clean Vehicle Interior:

1. Blow powder off or vacuum dash board and vehicle interior as required.

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 01-25-3
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
021201A	Perform Service Procedure To Clean Air-Conditioning Vents And Evaporator (F-150, Expedition And Navigator)	1.0 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
19860	D4

OASIS CODES: 208000, 208300