ELECTRICAL—AIR BAG WARNING LAMP ILLUMINATED WITH DIAGNOSTIC TROUBLE CODE DTC B2295 STORED IN MEMORY	Article No. 02-13-4

LINCOLN: 2001-2002 TOWN CAR

ISSUE

Some vehicles may exhibit an illuminated Air Bag warning lamp with Diagnostic Trouble Code (DTC) B2295, with Light Flashing Code 22 (Driver Seat Side Air Bag Circuit Fault), or Light Flashing Code 23 (Passenger Seat Side Air Bag Circuit Fault). This may be caused by Air Bag wiring harness.

ACTION

Install Service Wiring Harness Overlay Kit, part number 2W1Z-14B455-AA, using the Instruction Sheet found in the Repair Kit.

PART NUMBER	PART NAME
2W1Z-14B455-AA	Service Wiring Harness Overlay Kit - Air Bag Harness

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
021304A	Install Wiring Harness Overlay Kit	4.6 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
14A005	X2

OASIS CODES: 104000, 206000

Copyright © 2002 Ford Motor Company