INSTRUMENT CLUSTER INSPECTION AND/OR REPLACEMENT

AFFECTED VEHICLES: **CERTAIN 2001 MODEL YEAR TOWN CAR**

OVERVIEW

This document details the procedure for identifying affected Hybrid Electronic Cluster (HEC) modules by using the NGS or WDS service tools. HEC modules that are identified as affected components **must be** replaced.

INSPECTION/VERIFICATION

1. Using WDS or NGS, verify the Hybrid Electronic Cluster (HEC) module identification number.
   - If the number is either G1VF-10849-AA or G1VF-10849-BA, the HEC module must be replaced. Perform the Service Procedure that follows.
   - If the identification number is anything other than the two listed above, the HEC module does not need to be replaced. If the vehicle has any other no-start/intermittent no-start concerns, they are not related to this program. Perform normal no-start diagnostics as outlined in the appropriate service publication.

SERVICE PROCEDURE

NOTE: Make sure to obtain **ALL** of the customer's keys for HEC module replacement.

1. Replace the HEC module following the service procedure in Section 413-01 of the Town Car Workshop Manual.
2. Program all of the customer's keys to the ***new*** HEC module.
3. If the vehicle fails to start after replacing the HEC module and programming all the keys, disconnect the battery negative cable for ten minutes. Then follow the key programming sequence again.

Ford Motor Company

CPR © 2001 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
11/01