• **DRIVEABILITY—LOW SPEED SHUDDER ON LIGHT ACCELERATION—RANGER E.V. (ELECTRIC VEHICLE) ONLY** • **ELECTRICAL—ELECTRIC VEHICLE (E.V.)—LOW SPEED SHUDDER ON LIGHT ACCELERATION—RANGER E.V. (ELECTRIC VEHICLE) ONLY** • **ELECTRICAL—LOW SPEED SHUDDER ON LIGHT ACCELERATION—RANGER E.V. (ELECTRIC VEHICLE) ONLY**	**Article No. 00-22-5**

FORD: 1998-2000 RANGER

ISSUE

Some electric vehicles may exhibit a low speed shudder on light acceleration. This tip-in shudder may be caused by the Traction Inverter Module (TIM) electric motor control software.

ACTION

Install Traction Inverter Module (TIM) software version 20.0 (YL5F-14B298-AB). This software level can be obtained by calling the Ranger Electric Vehicle (EV) Hotline at 1-800-852-5280, 8:00 AM-5:00 PM Eastern Time, Monday-Friday. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

NOTE

THIS UPGRADE IS ONLY REQUIRED WHEN THE CUSTOMER HAS INDICATED THIS SHUDDER TIP-IN CONDITION.

1. Perform normal diagnostic tests as per the appropriate Ranger Workshop Manual.
2. Verify current TIM software level. (The current software level is YL5F-14B298-AA version 15.0.) If the current level of software is not installed, install the YL5F-14B298-AA version 15.0 software.

NOTE

THE VERSION 15.0 MUST BE INSTALLED BEFORE THE VERSION 20.0 UPGRADE CAN BE INSTALLED.

3. Perform upgrade with (YL5F-14B298-AB version 20.0) to the TIM using the Ranger EV Workshop Manual.
4. Recharge the vehicle's traction battery pack and perform a road test.

NOTE

RECHARGE TRACTION BATTERY PACK TO OP_STATE 87 PRIOR TO RELEASE TO CUSTOMER.

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
002205A	Install Traction Inverter Module (TIM) Software Version 20.0	0.8 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
14B298	42

OASIS CODES: 203000, 608500, 609500, 610500, 611500, 702200, 702300

Copyright © 2000 Ford Motor Company