• **LAMP—OIL WARNING LAMP ILLUMINATED—ELECTRIC VEHICLES ONLY** • **ENGINE—OIL WARNING LAMP ILLUMINATED—ELECTRIC VEHICLES ONLY**	**Article No. 00-26-2**

FORD: 1998-2001 RANGER

ISSUE

Some Ranger Electric Vehicles (EVs) and Electric Postal Chassis vehicles may exhibit intermittent lighting of the oil warning lamp. This oil warning lamp issue may be caused by the lack of time between data sampling of the Traction Inverter Module (TIM) and the transaxle.

ACTION

Install TIM software version 20.1 (YL5F-14B298-AC) and perform Oil Pressure Test. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Perform upgrade with (YL5F-14B298-AC version 20.1) to the TIM using the appropriate EV Ranger Workshop Manual.

NOTE

THIS SOFTWARE UPDATE (VERSION 20.1) CAN BE OBTAINED BY CALLING THE RANGER EV HOTLINE AT 1-800-852-5280, 8:00 AM-5:00 PM EASTERN TIME, MONDAY-FRIDAY.

NOTE

THIS SOFTWARE UPDATE (YL5F-14B298-AC VERSION 20.1) WILL ALSO BE AVAILABLE ON WORLDWIDE DIAGNOSTIC SYSTEM (WDS) RELEASE B-12, MARCH 2001.

2. Set the parking brake.
3. Remove the oil pressure port plug and install oil pressure test gauge (refer to the EV Ranger Workshop Manual).
4. Turn the ignition switch to the Start position, release and verify electric motor/transaxle is enabled.
5. With the electric motor/transaxle enabled, check the oil pressure on the oil pressure gauge. The oil pressure should stay steady (within 3 psi) and above 15 psi.
6. If the oil pressure is below the 15 psi specification, then the electric motor/transaxle may need to be replaced.

OTHER APPLICABLE ARTICLES: 00-22-5
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 203000, 204000, 206000, 401000, 505000, 510000

Copyright © 2000 Ford Motor Company