POWER WINDOWS—POWER WINDOWS MAY NOT OPERATE OR STICK TO WEATHERSTRIP	Article No. 00-26-3

FORD: 1996-2001 TAURUS

MERCURY: 1996-2001 SABLE

This article is being republished in its entirety to update the model years affected and to update the Service Procedure.

ISSUE

Some vehicles may exhibit a power window that will not operate downward because it's stuck/bound to the weatherstrip header. This may be due to infrequent use and environmental contaminants on the weatherstrip seal.

ACTION

Check window motor operation and lubricate the weatherstrip. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. With engine running, verify the power window operation by holding the power window switch in the down position for approximately 5 seconds. If window operates, proceed to Step 8. If window does not operate, proceed to Step 2.
2. Remove door trim panel.
3. Remove window motor from regulator and hook up a Digital Volt-Ohm Meter (DVOM) to measure DC volts at window motor connector.
4. With engine running, depress window switch (including driver master switch) and verify a minimum of 12V at motor connector. If voltage is OK, proceed to Step 5. If under 12 volts, investigate switch or other source of resistance.
5. Reconnect electrical connectors and function window motor.
6. If motor functions, reinstall motor. If motor exhibits lock-up, replace motor.
7. Pry the weatherstrip seal from the door glass along the header.
8. Lower the window and clean the weatherstrip glass run with a clean cloth that has been saturated with silicone spray (F5AZ-19553-AA).
9. Reinstall the door trim panel, if previously removed.
10. Verify smooth and proper operation.

PART NUMBER	PART NAME
F5AZ-19553-AA	Silicone Spray
F8DZ-5423395-AA	Window Motor - RH
F8DZ-5423394-AA	Window Motor - LH

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 98-25-13
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
002603AB	Check Window Motor Operation And Lubricate Weatherstrip (Two Or Three Doors)	0.3 Hr.
002603AC	Check Window Motor Operation And Lubricate Weatherstrip (All Doors)	0.4 Hr.
002603A	Check Window Motor Operation And Lubricate Weatherstrip (One Door)	0.2 Hr.
002603BB	Additional Time To Remove Trim Panel And Replace Window Motor (Two Doors)	1.0 Hr.
002603BC	Additional Time To Remove Trim Panel And Replace Window Motor (Three Doors)	1.2 Hrs.
002603BD	Additional Time To Remove Trim Panel And Replace Window Motor (All Doors)	1.5 Hrs.
002603B	Additional Time To Remove Trim Panel And Replace Window Motor (One Door)	0.6 Hr.

Copyright © 2000 Ford Motor Company

Article No. 00-26-3 Cont'd.

DEALER CODING

BASIC PART NO.	CONDITION CODE
5423394	41

OASIS CODES: 102000, 203000, 205000