- **NOISE—HIGH PITCHED GEAR "WHINE" HEARD WHILE DRIVING AND/OR COASTING AT LOW SPEEDS IN FIRST OR SECOND GEAR—VEHICLES EQUIPPED WITH 5R55N TRANSMISSION AND BUILT 3/15/1999 THROUGH 4/17/2000**
- **TRANSMISSION—5R55N—HIGH PITCHED GEAR "WHINE" HEARD WHILE DRIVING AND/OR COASTING AT LOW SPEEDS IN FIRST OR SECOND GEAR—VEHICLES BUILT 3/15/1999 THROUGH 4/17/2000**

Article No. 00-12-1

LINCOLN: 2000 LS

ISSUE

A high pitched gear "whine" while driving and/or coasting at low speeds in first or second gear may occur on some vehicles. This noise is caused by the mesh of the planetary gearset.

ACTION

Follow normal diagnostic procedures. If diagnosis shows that the components listed in the Noise/Vibration Routine are good, replace the forward planetary gearset and attaching components. Check Powertrain Control Module (PCM) calibration for latest level. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

CAUTION

ALL COMPONENTS FOUND IN THE SERVICE KIT MUST BE USED. FAILURE TO USE ALL KIT COMPONENTS AND REPROGRAM THE PCM (IF REQUIRED) MAY NOT ELIMINATE THE GEAR NOISE CONCERN, GENERATING A REPEAT REPAIR.

1. Follow normal diagnostic procedures as found in the current CD-ROM or Workshop Manual under Diagnosis by Symptom - Noise/Vibration. If diagnosis shows that the components listed in the Noise/Vibration Routine are good, follow the current published procedures for disassembly and reassembly and replace the forward planetary gearset and attaching components using new Service Kit YW4Z-7A398-SA.
2. Make sure that the vehicle has the latest PCM calibration level. If the vehicle does not have the latest calibration, reprogram the PCM.

PART NUMBER	PART NAME
YW4Z-7A398-SA	Planetary Gearset Kit

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
001201A	Replace The Forward Planetary Gearset (Includes Time To Remove And Install Transmission On Vehicles With 3.0L DOHC Engine)	5.8 Hrs.
001201B	Replace The Forward Planetary Gearset (Includes Time To Remove And Install Transmission On Vehicles With 3.9L DOHC Engine)	5.7 Hrs.
001201C	Reprogram Powertrain Control Module (PCM)	0.4 Hr.
001201D	Use "A" Time To Diagnose Per The Warranty And Policy Manual	

DEALER CODING

BASIC PART NO.	CONDITION CODE
7A398	12

OASIS CODES: 597997, 702000, 702200, 703200