NOISE—"FLUTTERING" FROM PCV VALVE WHEN VEHICLE IS TURNED OFF—VEHICLES BUILT 9/2/1999 THROUGH 10/1/1999	Article No. 00-2-1

FORD: 2000 FOCUS

ISSUE

There may be a "fluttering" noise from the PCV valve after engine shutdown on some vehicles. This may be caused by the PCV valve.

ACTION

Replace the PCV valve and hose. The revised PCV valve and hose should reduce the possibility of noise. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Remove the PCV hose from PCV valve and intake fitting.
2. Unscrew and remove old PCV valve.
3. Install new PCV Valve (YS4Z-6A666-AA).
4. Install new PCV Hose (YS4Z-6758-BA) onto PCV valve and intake fitting.

PART NUMBER	PART NAME
YS4Z-6A666-AA	PCV Valve
YS4Z-6758-BA	PCV Hose

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emissions Warranty Coverage

OPERATION	DESCRIPTION	TIME
000201A	Replace PCV Valve And Hose	0.2 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
6A666	30

OASIS CODES: 497000, 702100