TRANSMISSION—4R70W—OVERDRIVE INOPERATIVE—VEHICLES EQUIPPED WITH POLICE PACKAGE ONLY	Article No. 02-15-5

FORD: 2001-2002 CROWN VICTORIA

ISSUE

Some police package equipped Crown Victorias may exhibit a loss of 4th gear (overdrive). This may be caused by forced 4-2 downshifts (usually from high speeds). The original PCM (Powertrain Control Module) calibration may allow transmission component engagements during forced 4-2 downshifts in a manner that may lead to failure of the Overdrive (OD) Band.

ACTION

Verify the condition. Diagnose and service the Transmission per the Workshop Manual. Verify that the PCM calibration is at the latest level, if not, it must be reprogrammed. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Follow the normal diagnostic procedures to verify no 4th gear operation.
2. Replace the OD band if no 4th gear or slipping 4th gear. Follow all the normal procedures as shown in the Workshop Manual.
3. Use the procedures found in the Powertrain Control/Emissions Diagnosis (PC/ED) Workshop Manual and reprogram the PCM. Refer to the following PCM Calibration Information Chart.
4. Clear all Diagnostic Trouble Codes (DTC)s and validate service. If the condition is not corrected, continue with Diagnosis By Symptom as shown in the Workshop Manual.

PCM CALIBRATION INFORMATION

Application	Old Part Number (-12A650-)	Old Tear Tag	New Part Number (-12A650-)	New Tear Tag	Old Calibration	New Calibration	NGS/WDS Qualifier
2001-2002 Police Package	1W7A-FC	OFT2	1U7Z-DSA	SAQ0	1FB1PP0506	1FB1PP0506	WDS Release B19A.4 or Later
2001-2002 Police Package	1W7F-EG	BXT6	1U7Z-DZA	ZQM0	1FB1GP0511	1FB1GP0511	WDS Release B19A.4 or Later
2002 Police Package LWB	2W7A-LA	KSN0	2U7Z-BJA	TGT0	2FB1GL0500	2FB1GL0500	WDS Release B19A.4 or Later

Obtain an Authorized Modifications Decal (STAT 5941-2 - obtainable through the PDC) and list the date, dealer number, and summary of modifications performed. Select a prominent place adjacent to the Vehicle Emission Control Information Decal suitable for installing the Authorized Modifications Decal. Clean the area, install the decal, and cover it with a clear plastic decal shield.

Copyright © 2002 Ford Motor Company

AUTHORIZED MODIFICATIONS

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:
Reprogrammed Powertrain Control Module
(PCM) Per TSB 02-15-5
THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE, BY EPA AND CARB.
DEALER NUMBER: DATE:
CHANGE AUTHORITY:
FPS 8262 9/78 FORD MOTOR COMPANY PRINTED IN U.S.A.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 501000, 502000