NO START—VEHICLE PARKED ON INCLINE WITH VEHICLE NOSE DOWN AND 1/4 TANK OF FUEL	Article No. 99-22-3

FORD: 1997-2000 EXPLORER

MERCURY: 1997-2000 MOUNTAINEER

ISSUE

A no start condition when vehicle is parked on an incline with the vehicle in a nose down position and less than 1/4 tank of fuel may occur. This may be caused by the fuel pump sender assembly not reaching far enough into the front portion of the fuel tank reservoir when the vehicle is parked in this position.

ACTION

Replace fuel pump/sender assembly with a revised fuel pump/sender assembly. Refer to the appropriate model year Workshop Manual, Section 310-01, for removal and installation instructions.

PART NUMBER	PART NAME
XL2Z-9H307-DA	Fuel Pump/Sender Assembly (1999-2000)
F7PZ-9H307-BA	Fuel Pump/Sender Assembly (1997-1998)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage And Emission Warranty Coverage For 2000 Model Year Only

OPERATION	DESCRIPTION	TIME
992203A	Replace Fuel Pump	1.3 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
9H307	16

OASIS CODES: 404000, 603300