

State of Washington Department of Ecology

Ecology Inspector(s):

On-Site Representative
Name: n/a

Inspection Date and
Entry/Exit Time:
December 4, 2024,
11:28/11:47

Inspection Type:
Unannounced

Permit webpage:
[WAR313805](#)

The Good Neighbor Village project is covered under the State of Washington's Construction Stormwater General Permit (CSWGP). The CSWGP is a National Pollutant Discharge Elimination System (NPDES) and a State Waste Discharge permit for discharge of construction-related stormwater. The purpose of this inspection is to conduct a compliance inspection and to provide technical assistance as appropriate.

Ecology arrived on site to conduct a routine CSWGP compliance inspection. Responsible party or their representative were not present at the time of inspection. Site is actively importing material and utilizing tub grinders to make hog fuel mulch. Track out was observed on Spanaway Loop Road S. SWPPP was not reviewed during inspection.

Weather at time of inspection: 39 degrees Fahrenheit, mostly cloudy with a WSW wind at 1 mph.

Precipitation in the past 24 hours: No

UIC present: No

Section C: Compliance		
Violations and action required to achieve compliance	Complete or submit date	Guidance
<u>S9.D.2 Establish Construction Access</u> Track out was observed on Spanaway Loop Road S. BMP C105: Stabilized Construction Access requires maintenance where debris has filled the voids within the quarry spalls. Failure to meet S9.D.2.d: If sediment is tracked off site, clean the affected roadway thoroughly at the end of each day, or more frequently as necessary (for example, during wet weather). Remove sediment from roads by shoveling, sweeping, or pickup and transport of the sediment to a controlled sediment disposal area. Install and maintain adequate construction access to prevent track-out off-site.	Clean the affected roadway thoroughly at the end of each day, or more frequently as necessary	BMP C105, BMP C106, BMP C107
<u>S9.D.11 Maintain BMPs</u> BMP C105: Stabilized Construction Access requires maintenance where debris has filled the voids within the quarry spalls. Organic material/debris were observed within the quarry spill access. Maintain BMP C105: Stabilized Construction Access when the access is not preventing sediments from being tracked off site. Failure to meet S9.D.11.a: Permittee must maintain and repair all temporary and permanent erosion and sediment control BMPs as needed to assure continued performance of their intended function in accordance with BMP specifications. Maintain and repair all temporary and permanent BMPs, as set forth in permit condition S9.D.11.a.	Immediately begin. Address the problems no later than 10 days from the date of this inspection. 12/20/2024	SWMMWW, Chapter II-3 Construction Stormwater BMPs, C150, C160, C105

For assistance with any of these compliance issues or recommendations regarding BMPs, please see the 2019 Stormwater Management Manual for Western Washington (SWMMWW), Volume II, Construction Stormwater Pollution Prevention which includes BMPs for [Source Control](#) and [Runoff Conveyance and Treatment BMPs](#). The full SWMMWW is available at: <http://www.ecy.wa.gov/programs/wq/stormwater/manual.html>.

The Department of Ecology has the authority to issue formal enforcement actions including issuance of orders and civil penalties of up to \$10,000 per day per violation for violations of your NPDES permit and/or state laws and regulations.

Noncompliance with the limits, monitoring requirements, terms and/or conditions established in your permit may result in formal enforcement action by the Department of Ecology.

Ecology Inspector (signature): Joseph McCord Date: December 9, 2024
Ecology Inspector (print name): Joe McCord

Water Quality Program
Southwest Regional Office
PO Box 47775 Olympia, WA 98504-7775
SWRO Tel: 360-407-6300

All photos taken by Joe McCord

Photo 1

Photo Description: BMP C105: Stabilized Construction Access requires maintenance where organic debris/sediments have filled the voids within spalls.



Date:2024/12/04 Time:11:29:59 Lat:47.10080277777778 Long:-122.45091944444445 Direction degrees:54.691162109375

Photo 2

Photo Description: Track was observed traveling both directions on Spanaway Loop Road S.



Date:2024/12/04 Time:11:30:25 Lat:47.100975 Long:-122.4506138888889 Direction degrees:89.67916877850989

Photo 3

Photo Description: Track was observed traveling both directions on Spanaway Loop Road S.



Photo 4

Photo Description: Onsite operations observed during inspection were importing material and grinding organic material into hog fuel mulch.



Date:2024/12/04 Time:11:33:30 Lat:47.10043055555555 Long:-122.45176111111111 Direction degrees:323.74206578188114