## Alarm Help - MV SERIES -



ALARM ADDRESS	A1.5	ALARM NO.	1013
ALARM TEXT	SP H/L SPEED FUNC=>K5.0 SET ERR		
Related Signal	Input: X3.1 (Hi Speed), X3.2 (Low Speed) (MV154/154APC/MV204) •		
CAUSE	1: SPDL With Hi/Low Speed Control, But K5.0 = 0 . 2: SPDL Without Hi/Low Speed Control, But K5.0 = 1 .		
ACTION	Set Correct Data in Keep Relay 5 Bit 0 •		