Alarm Help - MV SERIES -



ALARM ADDRESS	A7.6	ALARM NO.	1146
ALARM TEXT	NO CONFIRM. OF WK-PIECE UNCLAMP.		
Related Sianal	Input: X3.6 (MV154/154APC/MV204) •		
	Output: Y3.7 (MV154/154APC/MV204) •		
CAUSE	When PMC turn OFF Work-piece clamp coil & over 5 seconds , the Work-piece		
	unclamp sensor not detected •		
	1. Check Work-piece unclamp sensor •		
	2. Check Work-piece clamp coil •		
	3. Check Air pressure •		