Stewardship for Falling Creek

Lead Steward: Andrew

2022-10-17

Boundary Issues

 $||\ ||\ ||\ ||$

Channel Issues

Year Subtype	Issue	Description	Treatment	TreatDatResolved
2022 Channel Sta- bility/Erosion	Slumping_Se	ttliDgainage from slope enters channel. Small holes in bank & portion of bank sloughed away.	Installed livestakes, plugs, and tried to plug the biggest hole	02/2022 No
2022 Channel Sta-	Erosion_Sco			No
bility/Erosion 2022 Needs				No
Livestakes 2022 Channel Sta-				No
bility/Erosion				NO
2022 Failed Structure	Erosion/Scou	redBMP failing? Drain tile seems messed up maybe? This could be the LOs repair in 2020		No
2022 Failed Structure		Widening bends, sediment flush, scour, log fallen into stream.		No
2022 Failed Structure		Confluence reveals incision in main stem. Headcut?		No
2021 Channel Sta- bility/Erosion	Erosion_Sco	ur Scour around and at bottom of lunker logs. Scour of outside bends.		Yes
2021 Failed Structure	Other	Soil behind lunker log washing out or slumping in	Added 5 plugs behind log	09/2021 Yes

Year	Subtype	Issue	Description	Treatment	TreatDatesolved
2021	Failed	Piping	Piping left side, no fabric. Update: log vane. No		Yes
	Structure		action needed $3/14/22$		
2021	Failed	Failed/Not			Yes
	Structure	Functional			
2021	Channel Sta-	Erosion_Scour	Scour on outside bends and behind lunker log. Add	Added plugs around banks, sill, and	09/2021 No
	bility/Erosion		livestakes.	lunker log	
2021	Channel Sta-	Erosion_Scour	Incision and scour on bends. Add live stakes.	Added 15 Juneus plugs to bends.	09/2021 No
	bility/Erosion				
2021	Channel Sta-	Erosion_Scour	Incision and scour		No
	bility/Erosion				
2021	Needs				No
	Livestakes				
2021	Needs				No
	Livestakes				
2021	Needs				No
	Livestakes				
2021	Channel Sta-	Aggradation_I	Deposit folks in with sand, channel hard to define		No
	bility/Erosion		around multi-stem willow. Remove willow?		
2021	Channel Sta-		Watch for stability where ATV used to drive across.		No
	bility/Erosion		Needs livestakes?		
2021	Failed	Erosion/Scoure	edLog sill Scoured around ends. Added plugs. Needs		No
	Structure		live stakes and sill shaving.		
2021	Failed	Other	Needs to pare down		No
	Structure				

Vegetation Issues

Weed Issues

Year Species1	Species2	Issue	Treatment	Method	TreatDatResolved
2022 Blackberry	Chinaberry	7			No
2022 Blackberry	OTHER	Cattails, Blackberry, Pines galore			No
2022 Chinaberry					No
2022 Chinese					No
Privet					
2022 Chinese		Lopper size, scattered			No
Privet					
2022 Japanese					No
Honeysuckle	;		6.14	D 1 1	0.0.10.000.34
2022 Lespedeza		from contaminated seed mix	foliar	Backpack Spray	06/2022 No
2022 Lespedeza					No
2022 OTHER	$\begin{array}{c} { m Sweet} \\ { m Gum} \end{array}$	Loblolly	Cut pines and cut stump sweetgum. Daylighting around trees overtopped by pine and sweetgum.	Mow	09/2022 Yes
2022 OTHER		Cattails in stream			No
2022 OTHER		Remove Willow from channel			No
2022 OTHER		cattails			No
2022 Tree Of					No
Heaven					
2021 Chinaberry		scattered smaller stems, 3 hack'n'squirt stems			Yes
2021 Chinaberry		Scattered stems			No
2021 Chinaberry		Saw size			No
2021 Chinaberry	Marsh Dewflower				No
2021 Chinese					Yes
Privet					
2021 Chinese		Size classes vary from	Privet removal around Chicory	Cut	06/2021 No
Privet		seedlings to saw size		Stump	
2021 Chinese		Size classes vary from	cut stump privet	Cut	07/2022 No
Privet		seedlings to saw size		Stump	
2021 Chinese		Some saw sized privet and			No
Privet		seedlings.			

Year Species1	Species2	Issue	Treatment	Method	TreatDatResolved
2021 Chinese					No
Privet					
2021 Mimosa					Yes
2021 Mimosa		1 stem			No
2021 Mimosa		Saw size 1 stem			No
2021 OTHER		Loblolly regen			No

Miscellaneous Issues

Year	Subtype	Issue_Desc	$Issue_LocationOrFeature$	Resolved
2022	Misc	Cattail patch	Other	No
2022	Misc	Cattail patch		No
2022	Misc	Gate		No
2022	Misc	Livestake outer bend, remove pines		No
2022	Misc	Needs plugs		No
2022	Misc	Chainsaw works in channel debris		No
2021	Misc	Add t-post to low area	Upland	No