Recall Notification

MITSUBISHI MOTORS

No.. 010067

Update 6/12/2013

November 2013

TO: **Dealer Principal/Service Managers**

SUBJECT: **11-12MY Triton & Challenger– Front Suspension Lower Control Arm Inspection**

In the interest of safety and customer satisfaction, Mitsubishi Motors Australia Limited (MMAL) is voluntarily recalling 11MY and 12MY Triton and Challenger vehicles as it has been identified that there is a potential that these vehicles may be affected by the problem described below.

Description of Problems and consequences.

There is a possibility of improper welding on Front Suspension Lower Control Arms (LCA) produced prior to Friday, 11 May 2012 which may result in the weld failing. If the weld fails, it will be readily detected by the driver as the vehicle will become unstable, pulling to either left or right side of the road. As a precaution prior to inspection, customers should operate the vehicle in a conservative manner to avoid excessive shock load on the parts that may be affected.

Please note that there have been no reports of LCA failure due to improper welding in the Australian market.

Recall Procedure

As this is a potential safety related issue, this recall is being conducted as an advertised Safety Related Recall in line with the FCAI “Uniform Code of Practice”.

Owner Notification

All owners of affected vehicles will be contacted by mail at their last known address and requested to contact the nearest authorised Mitsubishi dealer to make an appointment to have the vehicle repaired.

Affected vehicles

Affected vehicles are contained within the following VIN ranges.	
11~12MY Triton 2WD	MMAENKA40BD015350 ~ MMAJYKA40CD012449
11~12MY Triton 4WD	MMACNKB40BD015437 ~ MMAJYKB40CD013855
11~12MY Challenger 2WD	MMAGNKG40CF000004 ~ MMAGYKG40CF002509
11~12MY Challenger 4WD	MMAGNKH40BF001929 ~ MMAGYKH40CF002541

For specific vehicle identification by VIN, check the current status via the Recall and Service campaigns facility in the dealer portal.

A total of 20405 vehicles are affected.

Dealer Responsibility

When an owner presents a vehicle that may be in the affected range, dealers are expected to confirm whether it is subject of an outstanding campaign by performing a SAP Vehicle search and complete the recall campaign as required.

This action is expected irrespective of whether or not the owner presents an “Owner Advice Mailer”

As detailed in Section11.13.1 of the Service Procedure Manual, if an Owner Letter is addressed to your dealership you must ensure that you correct the vehicle prior to sale or, if sold, **make every possible effort to contact the current owner** and arrange for rectification to be performed.

Repair procedure

The repair process is to check the welding condition by using the supplied special tools as detailed in the attached rectification procedure and judgement guide.

Note (1) The special tools MW400107 (5 items) have been sent by mail to the Service Manager.



Note (2) The anticipated incidence rate of improper welding is:
LH approximately 1 in 80 vehicles, RH approximately 1 in 35 vehicles.

Campaign Material

An initial “consignment” stock of one LH and 1 X RH Lower Control Arms has been dispatched to each dealer via normal parts dispatch to your parts department.

Replacement LCA’s will be supplied **FOC** upon receipt of a dealer order using the recall parts facility in the dealer portal.

Split pins are to be purchased via standard service parts channels. The recall parts handling allowance has been increased to $12.00 for this campaign to cover the cost of the split pins.

Note: All “consignment parts” not used/returned will be reconciled at actual replacement cost value.

When to replace	Part Number	Description	Qty	Order Method
Only if No Good	4013A335	LOWER ARM KIT,LH	1	Recall order process
Only if No Good	4013A336	LOWER ARM KIT,RH	1	Recall order process
Only if LCA Replaced	MF472085	PIN-SPLIT-4X30MM	1 per LCA	Standard parts order
Only if LCA Replaced	MF472086	PIN-SPLIT-4X35MM	1 per LCA	Standard parts order
Only if LCA Replaced	MF472069	PIN-SPLIT-3X25MM	2 per LCA	Standard parts order

Warranty Claim Procedures.

Claims can only be submitted by electronic warranty claim procedure. Do not return the recall program mailer, attach it to a copy of the repair order and retain it with the vehicle history file.

Claiming procedure

Note (1) The Lower Control Arms are sourced via the **recall parts procurement procedure**.
Note (2) Split pins are sourced via **STANDARD** parts channels.

Campaign 010067	Inspection Only	Inspection + replacement of Lower Arm, LH	Inspection + replacement of Lower Arm, RH	Inspection + replacement of both Lower Arms (LH & RH)
Claim Type	S	S	S	S
Position Code	010067	010067	010067	010067
Diagnosis Code	RC	RC	RC	RC
Operation Code	01006730	01006711	01006712	01006713
Labour Allowance	1.7 hr*	4.5 hr*	4.5 hr*	6.3 hr*
Causal Part No	NFP	1 x 4013A335 (LH LCA $0.00)	1 x 4013A336 (RH LCA $0.00)	1 x 4013A335 (LH LCA $0.00)
Additional Part/s		RCHANDLING ($12.00)	RCHANDLING ($12.00)	1 x 4013A336 (RH LCA $0.00)
				RCHANDLING ($12.00)
Removed Parts	N/A	Retain for 90 days after claim payment for inspection then Destroy	Retain for 90 days after claim payment for inspection then Destroy	Retain for 90 days after claim payment for inspection then Destroy
Note" The increased parts handling is to compensate for purchasing the split pins listed in "Campaign Material" section when replacing the lower control arms.				

*(including ALL allowances)

Should you require any further information relating to this campaign please contact the Dealer Assistance Centre (select option 4 then press 4).

Yours sincerely,
Mitsubishi Motors Australia Limited



D. R. Budden
Head of Service Manager