MMAL DEALER BULLETIN

Bulletin Subject	**Outlander Steering Wheel Touch Sensor Recall**		
Applicable Model(s)	23-24MY Outlander fitted with MI-PILOT		
Notice Category	**Recall Campaign**	Technical Bulletin	**010175**
Service Group	37 Steering	Latest Revision Issued	13/06/2025
Revision	A	MMAL Reference	SSI2502001

Printed copies may not reflect the latest updates. Please consult the online version

Mitsubishi Motors Australia Limited (MMAL) is conducting a safety related vehicle recall campaign (effective from 28/03/2025) to rectify issues relating to ZM Outlander vehicles fitted with MI-PILOT.

Dealer Responsibility

When an owner presents a vehicle, dealers are expected to confirm whether it is the subject of any outstanding campaigns by performing a Vehicle Search in the Warranty Portal, and complete the campaigns as required.

Product Description

23MY and 24MY ZM Outlander Exceed and Exceed Tourer (incl. PHEV) built prior to 26th October 2023.

7,489 vehicles affected.

Concern

When using MI-PILOT, the MI-PILOT function may stop along with a system failure warning, or the hands-off warning may not be displayed even when the driver takes their hands off the steering wheel.

Risk

If the MI-PILOT system does not operate as intended, it increases the risk of serious injury or even result in death to anyone located in the vehicle, or other road users.

Cause

The electrode plating on the components built into the steering wheel was cracked, resulting in poor continuity.

Production Fix

Conductive cloth tape was added inside the steering wheel to ensure a conductive path.

Model	Breakpoint VIN	Production Fix Data
ZM Outlander	JMFXTGM4WRZ004426	26/10/2023
ZM Outlander PHEV	JMFXDGN0WRZ001183	26/10/2023

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Outlander Steering Wheel Touch Sensor Recall**		
Applicable Model(s)	23-24MY Outlander fitted with MI-PILOT		
Notice Category	**Recall Campaign**	Technical Bulletin	**010175**
Service Group	37 Steering	Latest Revision Issued	13/06/2025
Revision	A	MMAL Reference	SSI2502001

Rectification Procedure

1. Before commencing work:

- **Photograph the VIN stamping** for attachment to the repair order and claim
- **Photograph the odometer reading** for attachment to the repair order and claim
- Check the vehicle VIN matches the VIN printed on the repair order
  STOP work if the VIN does not match, and clarify the correct vehicle

2. Confirm the product date of the steering wheel and, if it is an affected one, replace the steering wheel and associated parts (MMAL expect over 99% of vehicles will require replacement parts).

A Take a clear photo the steering wheel product date and submit with the claim

Refer to the *010175 Steering Wheel Replacement Procedure*.

Parts Order Information

MMAL expect that over 99% of vehicles will require replacement parts. Ensure the following parts are ordered and on-hand prior to the recall appointment to avoid a second visit by the customer.
If the parts are not used, MMAL will cover the return cost (Claim Reason – Recall Return)

Part No.	Part name	Qty per Vehicle	Order Type
MW400340	Steering wheel ASSY	1	ZREC (VIN based order)
MW400341	Steering wheel bolt	1	
MW400346	Steering switch ASSY*	1	
Removed components are to be destroyed			

** MW400346 includes both LH and RH switches*

Campaign Claim Procedure

A Submit a claim for this Recall Campaign via the MMAL warranty portal and include a clear photograph of the steering wheel product date.

Campaign	Claim Options	Labour Details	
		Operation	Time
010175	Inspection Only	01017530	0.4H
	Inspect and Replace	01017510	0.9H
	Inspect, Replace & Tie Rod Adjust	01017540	1.4H

Revision Details

Initial Release – No revision applicable.
Rev A – Photo of steering wheel product date required for claim submission

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.