Service Campaign

Campaign No 020116

Date September 2014

MITSUBISHI MOTORS

Bulletin Distribution **Revision 6** **29/03/2022** **(Part No updates)**

X	Dealer Principal	X	Service Manager	X	Service Staff
X	Parts Manager	X	Parts Staff		Pre delivery Manager

Subject: 4D56 Hi Power Overheat Triton and Challenger

Description of Problem and Prevention

- MMC has advised that Triton and Challenger equipped with 4D56 High-Power engines may exhibit a symptom of overheat caused by the loss of coolant.
- As preventive action, the following corrective measures are implemented:
  - Replacing the radiator cap with a high-valve-opening-pressure type
  - Replacing the coolant (increase concentration from 30% to concentration 50%)
  - Reprogram of ECU (for early detection of coolant loss to prevent damage to the engine)

Cause

- Engine overheat may occur due to excessive loss of coolant that may be caused by repetitive coolant evaporation.
- Localised coolant evaporation could also occur after high load driving such as towing heavy cargo.
- Also, if the sealing condition is not adequate at the upper surface of cylinder block (due to the surface roughness) engine coolant blow-by may occur promoting overheat.

Production Fix

- Radiator cap valve opening pressure changed from 109kPa to 1**27kPa** effective 21/02/2014
- Coolant concentration changed from 30% to **50%** effective 22/11/2013
- ECU program changed to add coolant loss detection function (CEL*- on and engine output restriction in case of detecting coolant loss) effective 09/09/2013
  **CEL=Check Engine Lamp*
- Improved smoothness of upper surface of cylinder block for engines built on and after 18/03/2014 (engine number 4D56 UCFA9504 onwards)

Affected Vehicles

Applicable vehicles will be loaded in the dealer portal and will be identified by a vehicle enquiry.

A total of 76,982 vehicles are involved in the campaign.

For specific vehicle identification by VIN, check the current status via the Service Vehicle Search facility in the dealer portal.

Note: Only the nominated vehicles require preventative action and not all vehicles require all three actions.

Field Action Required – Refer to the rectification attachment for full details

- There are 3 items to be applied, however **not all items apply to every vehicle** and some vehicle's may require additional repair action. Check the applicable items for each VIN by using the supplied "Warranty Application" and the attached rectification procedures.
  - Radiator Cap replacement - all vehicles
  - Coolant Replacement - 95% of vehicles
  - ECU Reprogram - 86% of vehicles

Parts Information

1) Replacement Part

Part Name	Part Number	Quantity	Remarks
CAP, RADIATOR	R1350A920	1	Valve opening pressure 127kPa

2) Coolant (All Affected Vehicles)
Please replace full quantity of coolant with concentration 50% type.

Part Name	Claim Part Number	Quantity	Remarks
Mitsubishi Genuine Long life coolant (premixed green)	COOLANT	8.2L	Concentration 50%

3) Engine ECU Reprogramming (All affected vehicles)
Please update ECU program to the latest version using MUT-III.

The Software Version Table identifies the relevant version number.
CD-ROM CD3A14051 has been sent to dealers as detailed in General Letter GL-14-019.

Vehicle Specification	Data No	ECU P/No.	Software Number	
			New	Old
10MY CR 4D56 EURO4 5AT 4WD H/P	1862B775	1860B241	1860B241 06	1860B241 05 - 01
10MY CR 4D56 EURO4 5MT 4WD H/P	1862B776	1860B347	1860B347 04	1860B347 03 - 01
10MY CR 4D56 EURO4 4AT 4WD H/P	1862B777	1860B348	1860B348 07	1860B348 06 - 01
11-13MY CR 4D56 EURO4 5MT 2/4WD H/P	1862B778	1860B583	1860B583 06	1860B583 05 - 01
11-14MY CR 4D56 EURO4 4AT 2/4WD H/P	1862B770	1860B584	1860B584 07	1860B584 06 - 01
11-14MY CR 4D56 EURO4 5AT 2/4WD H/P	1862B771	1860B585	1860B585 06	1860B585 05 - 01
14MY CR 4D56 EURO4 5MT 2/4WD H/P	1862B772	1860C267	1860C267 02	1860C267 01
09-10MY CR45 4D56 EURO4 5AT 4WD H/P	1862B779	1860B208	1860B208 05	1860B208 04 - 01
09-10MY CR45 4D56 EURO4 5MT 4WD H/P	1862B780	1860B210	1860B210 05	1860B210 04 - 01
11-13MY CR454D56 EURO4 5MT 2/4WD H/P	1862B781	1860B554	1860B554 06	1860B554 05 - 01
11-14MY CR454D56 EURO4 5AT 2/4WD H/P	1862B773	1860B555	1860B555 05	1860B555 04 - 01
14MY CR45 4D56 EURO4 5MT 4WD H/P	1862B774	1860C272	1860C272 02	1860C272 01

Note: Installing the software update will result in all previously issue updates being installed.

4) In case coolant blow-by is observed, the necessary parts in the table below must be ordered via standard service parts order processes.

Operation Performed	Applicable Models	Part Name	Part No.	Quantity	Remarks
Long Engine replacement	Refer to ASA CAPS PNC 01015A	ENGINE ASSSY, LONG	10105W230P	1	
Additional Parts for long engine replacement					
Long Engine replacement	All	GASKET KIT, ENGINE OVERHAUL	1000D334	1	Long engine replacement (Additional Parts)
	All	GASKET, EXHAUST PIPE	MB687002	1	
	All	GASKET, EXHAUST PIPE	MR529716	1	
	All	TUBE-FUEL INJECTION-NO.1	1428A044	1	
	All	TUBE-FUEL INJECTION-NO.2	1428A166	1	
	All	TUBE-FUEL INJECTION-NO.3	1428A045	1	
	All	TUBE-FUEL INJECTION-NO.4	1428A034	1	
	All	TUBE SET-FUEL INJECTION	1428A165	1	

Note: The following parts can be used ONLY if a long engine is **NOT available**

Operation Performed	Applicable Models	Part Name	Claim Part No.	Quantity	Remarks
Short Engine Replacement	All	ENGINE ASSY, SHORT	10103W070P	1	All MMAL 4D56 Hi Power
	All	CYLINDER HEAD ASSY	1005B453	1	These parts are used only when replacing short engine.
	All	GASKET KIT, ENGINE OVERHAUL	1000D334	1	
	All	BOLT, CYLINDER HEAD	1005B373	18	
	All	WASHER, CYLINDER HEAD BOLT	1005B594	18	
	All	GASKET, EXHAUST PIPE	MB687002	1	
	All	GASKET, EXHAUST PIPE	MR529716	1	
	All	O-RING, VACUUM PUMP	2020A008	1	
	All	O-RING, VACUUM PUMP	2020A009	1	
	All	RTV SEALANT	SEALANT	As Req.	
	All	OIL FILTER	1230A186	1	
	All	BELT, VALVE TIMING	1145A019	1	
	All	BELT, BALANCER TIMING	1145A081	1	
The following (A) or (C) cylinder head gaskets may be required, depending on the new short motor piston protrusion that you measure.					
Short Engine Replacement (Only if required)	All	GASKET, CYLINDER HEAD (A)	1000D333	(1)*	*Cylinder Head (B) is included in the Gasket Kit, Engine Overhaul. (A) and (C) shall be used when necessary after measuring piston proturusion in accordance with W/S manual.
	All	GASKET, CYLINDER HEAD (C)	1000D335	(1)*	

* Part numbers for short engine replacements are listed here to be used ONLY if a long engine is not available.

Warranty Claim Procedures

Claims can only be submitted by electronic warranty claim procedure.

Due to the complex nature of operation codes, all claims **MUST** be prepared using the Warranty Application provided by the warranty department.

The Warranty Application will generate the claim with the applicable position, quality and labour operation codes, based on the work **you confirm** is being performed for the specific vehicle.

Parts Hold Requirements

In the case of an engine replacement, all parts MUST be retained for 90 days from the claim payment date.

Should you require any further information relating to this campaign, please contact the Dealer Assistance Centre on 1300 1300 99.

Others

Instructions/recommendations for dealers and customers:

- A new DTC of P0217 (Engine Coolant Over Temperature Condition) has been added as a result of ECU reprogramming. In case coolant temperature reaches an abnormal range, The ECU will detect the condition and set this DTC. At the same time, ECU will turn the CEL (Check Engine Lamp) on and restrict engine output to protect the engine from heat damage. If this DTC is detected on a vehicle after ECU reprogramming, the cooling system needs to be inspected as there is a possibility of engine overheat.
- As part of this campaign the vehicle cooling system will be filled with high concentration type coolant. Please ensure service personnel recommend customers to use the same type of coolant (50%) for all future refills/replacement.
- In the event that completion of this Service Campaign coincides with a scheduled coolant change, the customer invoice should be reduced by the cost of the coolant change.
- If the coolant has recently been changed, there will be no customer reimbursement, however the coolant must be replaced again.
- After coolant replacement (as part of this campaign) the next replacement should still be carried out at the next scheduled interval.

Regards

Yasuhiro Oda
Deputy Director Aftersales