# MMAL DEALER BULLETIN

| | | | |
|---|---|---|---|
| Bulletin Subject | **Eclipse Cross PHEV Fuel Maintenance** | | |
| Applicable Model(s) | 22-24MY Eclipse Cross PHEV | | |
| Notice Category | **Service Campaign** | Technical Bulletin | **020219** |
| Service Group | 13 Fuel | Latest Revision Issued | 01/07/2025 |
| Revision | N/A | MMAL Reference | SSI2505003 |

**Printed copies may not reflect the latest updates. Please consult the online version**

Mitsubishi Motors Australia Limited (MMAL) is conducting a Service Campaign (effective from 02/07/2025) to rectify an issue on Eclipse Cross PHEV.

## Dealer Responsibility

Dealers must check whether a vehicle has any outstanding campaigns by performing a Vehicle Search in the Warranty Portal and complete all outstanding campaigns as required. This must be done whenever an owner makes a service booking or presents a vehicle, or during new or used vehicle PDI.

**IMPORTANT**

**When making a service booking to have this campaign completed instruct the customer to present their vehicle with less than 50% charge on the drive battery**

## Product Description

22MY to 24MY YB Eclipse Cross PHEV built prior to 16th December 2024.
6,664 vehicles affected.

## Concern

The PHEV fuel maintenance program designed to prevent old fuel from remaining in the tank when not used for a long period of time does not function.
If at least 15L of fuel is not added at one time within approximately 3 months, a message should prompt the owner to add at least 15L of fuel, or the engine should start automatically to consume the old fuel.

## Risk

Old fuel can deteriorate if it remains unused in the tank for an extended period, potentially causing clogging or rust in the fuel tank, pump, pipes, injectors, and other components.

## Cause

Insufficient ECU programming.

## Production Fix

The ECU programming was updated.

| Model | Breakpoint VIN | Production Fix Data |
|---|---|---|
| YB Eclipse Cross PHEV | JMFXDGL3WRZ004022 | 16/12/2024 |



**Disclaimer:** The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
**Note:** Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

**Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.**

| | | | |
|---|---|---|---|
| Bulletin Subject | **Eclipse Cross PHEV Fuel Maintenance** | | |
| Applicable Model(s) | 22-24MY Eclipse Cross PHEV | | |
| Notice Category | **Service Campaign** | Technical Bulletin | **020219** |
| Service Group | 13 Fuel | Latest Revision Issued | 01/07/2025 |
| Revision | N/A | MMAL Reference | SSI2505003 |

## Rectification Procedure

1. Before commencing work:

- **Photograph the VIN stamping** for attachment to the repair order and claim
- **Photograph the odometer reading** for attachment to the repair order and claim
- Check the vehicle VIN matches the VIN printed on the repair order
  **STOP work if the VIN does not match, and clarify the correct vehicle**

2. Conduct engine inspection (DTC check) and reprogram the ECU.

| Data No. | New HW Part No | New SW Part No/Ver | Current HW Part No | Current SW Part No/Ver |
|---|---|---|---|---|
| 1862D259 | 1860D697 | 1860D69701 | 1860D697 | 1860D69700 |

Carefully follow the ***020219 Work Instructions***

## Parts Order Information

No parts are required to update the ECU. However, if any abnormalities are found during the engine inspection, please follow the workshop manual (troubleshooting) for appropriate action.

## Campaign Claim Procedure

Submit a claim for this Service Campaign via the MMAL Warranty Portal.

| Campaign | Claim Options | Labour Details | |
|---|---|---|---|
| | | Operation | Time |
| 020219 | Reprogram ECU | 02021913 | 0.5H |

### Additional Expenses

If additional work is required after the engine inspection (as per the work instructions), then submit a SCA using **020219** as the position code after the repair has been completed using labour and parts as required.

## Revision Details

Initial Release – No revision applicable.



**Disclaimer:** The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
**Note:** Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

**Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.**