MMAL DEALER BULLETIN

This PDI Campaign resumes 23/03/2026

MITSUBISHI MOTORS

Bulletin Subject	**ASX TSR (Traffic Sign Recognition) – NOADR**		
Applicable Model(s)	25MY ASX (LS only)		
Notice Category	**PDI Campaign**	Technical Bulletin	**020221**
Service Group	54 Chassis Electrical	Latest Revision Issued	22/10/2025
Revision	N/A	MMAL Reference	PDI251017

Printed copies may not reflect the latest updates. Please consult the online version

Mitsubishi Motors Australia Limited (MMAL) is conducting a PDI campaign (effective from 23/10/2025) to rectify an issue on 25MY ASX.

Dealer Responsibility

Dealers must check whether a vehicle has any outstanding campaigns by performing a Vehicle Search in the Warranty Portal and complete all outstanding campaigns as required. This must be done whenever an owner makes a service booking or presents a vehicle, or during new or used vehicle PDI.

IMPORTANT

THIS PDI CAMPAIGN MUST BE COMPLETED BEFORE HAND-OVER TO THE CUSTOMER

Product Description

25MY XE ASX (LS only) built prior to 30 August 2025.
851 vehicles affected.

Concern

TSR (Traffic Sign Recognition) does not display speeds above 80 km/h

Cause

Wrong Configuration file leading to TSR (Traffic Sign Recognition) not displaying speeds above 80km/h in Australia.

Production Fix

New Configuration has been checked and validated.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.

Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**ASX TSR (Traffic Sign Recognition) – NOADR**		
Applicable Model(s)	25MY ASX (LS only)		
Notice Category	**PDI Campaign**	Technical Bulletin	**020221**
Service Group	54 Chassis Electrical	Latest Revision Issued	22/10/2025
Revision	N/A	MMAL Reference	PDI251017

Rectification Procedure

1. Before commencing work:

   - **Photograph the VIN stamping** for attachment to the repair order and claim
   - **Photograph the odometer reading** for attachment to the repair order and claim
   - Check the vehicle VIN matches the VIN printed on the repair order
     STOP work if the VIN does not match, and clarify the correct vehicle

2. Connect battery charger to vehicle
3. Update software for **NOADR** according to the work procedure - Ref. **020221 Work Procedure (NOADR)**
4. Leave vehicle off and locked for 15 minutes
5. Attach a copy of the updated ECU Identification file to the claim

Parts Order Information

No parts are required.

Campaign Claim Procedure

Submit a claim for this PDI Campaign via the MMAL Warranty Portal.

Campaign	Claim Options	Labour Details	
		Operation	Time
020221	Reprogram TSR - NOADR	02022113	0.3H

Revision Details

Initial Release – No revision applicable.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.