MMAL DEALER BULLETIN

This PDI Campaign resumes 23/03/2026

MITSUBISHI MOTORS

Bulletin Subject	**ASX Service Interval (Small Cluster)**		
Applicable Model(s)	25MY ASX (LS only)		
Notice Category	**PDI Campaign**	Technical Bulletin	**020223**
Service Group	54 Chassis Electrical	Latest Revision Issued	22/10/2025
Revision	N/A	MMAL Reference	N/A

Printed copies may not reflect the latest updates. Please consult the online version

Mitsubishi Motors Australia Limited (MMAL) is conducting a PDI campaign (effective from 23/10/2025) to rectify an issue on 25MY ASX.

Dealer Responsibility

Dealers must check whether a vehicle has any outstanding campaigns by performing a Vehicle Search in the Warranty Portal and complete all outstanding campaigns as required. This must be done whenever an owner makes a service booking or presents a vehicle, or during new or used vehicle PDI.

IMPORTANT

THIS PDI CAMPAIGN MUST BE COMPLETED BEFORE HAND-OVER TO THE CUSTOMER

Product Description

25MY XE ASX (LS Only) built prior to 25 July 2025.
694 vehicles affected.

Concern

Service interval was set at 12 month/30,000km (not 12month/15,000km)

Cause

Wrong Configuration file

Production Fix

New Configuration has been checked and validated.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**ASX Service Interval (Small Cluster)**		
Applicable Model(s)	25MY ASX (LS only)		
Notice Category	**PDI Campaign**	Technical Bulletin	**020223**
Service Group	54 Chassis Electrical	Latest Revision Issued	22/10/2025
Revision	N/A	MMAL Reference	N/A

Rectification Procedure

1. Before commencing work:

- **Photograph the VIN stamping** for attachment to the repair order and claim
- **Photograph the odometer reading** for attachment to the repair order and claim
- Check the vehicle VIN matches the VIN printed on the repair order
  STOP work if the VIN does not match, and clarify the correct vehicle

2. Connect battery charger to vehicle
3. Update software for **Small Cluster** according to the work procedure - Ref. **020223 Work Procedure (Small Cluster)**
4. Leave vehicle off and locked for 15 minutes

Parts Order Information

No parts are required.

Campaign Claim Procedure

Submit a claim for this PDI Campaign via the MMAL Warranty Portal.

Campaign	Claim Options	Labour Details	
		Operation	Time
020223	Reprogram Servc Intrvl (Sml Cluster)	02022313	0.3H

Revision Details

Initial Release – No revision applicable.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.