MMAL DEALER BULLETIN

Bulletin Subject	**Mi-Display to Alpine**		
Applicable Model(s)	MR Tritons fitted with a Mi-Display unit		
Notice Category	**Service Campaign**	Technical Bulletin	**020225**
Service Group	54 Chassis Electrical	Latest Revision Issued	20/08/2026
Revision	D	MMAL Reference	N/A

⚠ Printed copies may not reflect the latest updates. Please consult the online version

Mitsubishi Motors Australia Limited (MMAL) is conducting a service campaign (effective from 16/12/2025) to replace the Mi-Display unit with an Alpine unit (conditions apply).

Dealer Responsibility

Dealers must check whether a vehicle has any outstanding campaigns by performing a Vehicle Search in the Warranty Portal and complete all outstanding campaigns as required. This must be done whenever an owner makes a service booking or presents a vehicle, or during new or used vehicle PDI.

Product Description

Campaign No	Mi-Display Part No	Alpine Part No	Alpine Part Description
020225	AU600034 (Non GLX)	EG100148	Display Multivision Kit (includes new user manual)
		EG100164	Audio Equipment Kit (External GPS Antenna)
	AU600035 (GLX only*)	EG100148	Display Multivision Kit (includes new user manual)
		EG100164	Audio Equipment Kit (External GPS Antenna)
		EG100208	Display Multivision Harness (MR-GLX) (only until stock is depleted)
		TRANSITIONING TO:	
		EG100215	Display Multivision Kit (MR-GLX)
		EG100164	Audio Equipment Kit (External GPS Antenna)
Retain the removed Mi-Display unit for 90 days then destroy			

D

*GLX has manual A/C controls (GLX+ and GLX-R have auto A/C and are Non GLX)

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Mi-Display to Alpine**		
Applicable Model(s)	MR Tritons fitted with a Mi-Display unit		
Notice Category	**Service Campaign**	Technical Bulletin	**020225**
Service Group	54 Chassis Electrical	Latest Revision Issued	20/08/2026
Revision	D	MMAL Reference	N/A

Pre-Conditions

Replacement of the Mi-Display unit with an Alpine unit will be completed on vehicles that have either had:

- At least one Mi-Display exchange unit previously fitted.
  OR
- Previously documented (noted on RO's) concerns with original unit without a replacement being fitted.

If the vehicle is experiencing a first-time failure of the Mi-Display unit with no previously reported concerns, the standard Mi-Display exchange procedure is to be followed.

Process

- Confirm either that:
  - At least one Mi-Display exchange unit previously fitted in the vehicle; or
  - Previous concerns have been noted on RO's with the original unit.
  - **Obtain Customer consent to replace Mi-Display unit with Alpine unit.**
- Submit MiDealer Assist case with the required documents and trouble-shooting guide competed (refer to the Rectification Procedure below for details)
- MMAL will review each case and determine if an Alpine unit is approved.
- Once approved, VIN will be loaded into this Service Campaign. Dealer will receive confirmation via MiDealer Assist case that parts can be ordered.
- For non GLX models - install new Alpine unit, new microphone, external GPS antenna and fascia and test that all OK.
- D For GLX models only- replace harness to new Alpine unit (only until GLX harness parts are depleted), install Alpine unit, new microphone, external GPS antenna and fascia and test that all OK.
- Remove the old audio user manual (if in vehicle) and place new Alpine user manual in the glovebox.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Mi-Display to Alpine**		
Applicable Model(s)	MR Tritons fitted with a Mi-Display unit		
Notice Category	**Service Campaign**	Technical Bulletin	**020225**
Service Group	54 Chassis Electrical	Latest Revision Issued	20/08/2026
Revision	D	MMAL Reference	N/A

Parts Order Information

For non GLX models - Dealer must order and fit both parts.

Part No.	Part name	Qty per Vehicle	Order Type
EG100148	Display Multivision Kit	1	**ZREC** (VIN based order)
EG100164	Audio Equipment Kit (External GPS Antenna)	1	
Removed components are to be retained for 90 days then destroyed			

For GLX models only - Dealer must order and fit all three parts.

Part No.	Part name	Qty per Vehicle	Order Type
EG100148	Display Multivision Kit	1	**ZREC** (VIN based order)
EG100164	Audio Equipment Kit (External GPS Antenna)	1	
EG100208	Display Multivision Harness (MR-GLX)	1	
Removed components are to be retained for 90 days then destroyed			

Once stock of EG100208 GLX Harness is depleted, GLX parts will transition to:

Part No.	Part name	Qty per Vehicle	Order Type
EG100215	Display Multivision Kit (MR-GLX)	1	**ZREC** (VIN based order)
EG100164	Audio Equipment Kit (External GPS Antenna)	1	
Removed components are to be retained for 90 days then destroyed			

D

Ensure the correct parts are ordered as per MMAL's instructions on the Mi-Dealer Assist case reply.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Mi-Display to Alpine**		
Applicable Model(s)	MR Tritons fitted with a Mi-Display unit		
Notice Category	**Service Campaign**	Technical Bulletin	**020225**
Service Group	54 Chassis Electrical	Latest Revision Issued	20/08/2026
Revision	D	MMAL Reference	N/A

Rectification Procedure

Before commencing any work, the following steps **MUST** be followed:

1. Check the vehicle VIN matches the VIN printed on the repair order.
   STOP work if the VIN does not match and clarify the correct vehicle.
2. Confirm that Customer has at had either:
   a. At least one audio unit replaced: or
   b. Multiple reported concerns with original unit without a replacement unit being fitted.
   c. If this is the first fault with no previously reported concerns, then follow the standard Mi-Display exchange procedure.
3. Photograph the VIN stamping for attachment to the repair order and claim.
4. Photograph the odometer reading for attachment to the repair order and claim.
5. Photograph the audio unit screen showing software version (settings/information) for attachment to the repair order and claim.
6. Where unit has previously been replaced, take video evidence of the Customers concern (where possible) for attachment to the claim.
7. Where unit has not been replaced but has experienced multiple issues, obtain copies of RO's for attachment to the claim.
8. Complete the required troubleshooting guide ("Mi-Display Troubleshooting Guide") for attachment to the repair order and claim.
9. Log into MiDealer Assist and create a case using the following information:
   a. Title – "MMAXXXXXXXXXXXXXX" (ensure that the correct VIN is entered).
   b. Case Topic – select "MiCare".
   c. Case Subtopic – select "MiCare – 020225 Mi-Display to Alpine".
   d. The following documents **MUST** be attached to the case:
      i. Photo of the VIN.
      ii. Photo of the audio unit screen showing software version (settings/information).
      iii. Copy of completed trouble shooting guide.
      iv. Evidence of the fault (video/s if possible).
      v. Copy of all RO's where concern has been reported/noted (only where unit has not yet been replaced).
10. Once the Alpine unit is approved:
    a. MMAL will load the VIN into 020225 service campaign.
    b. Dealer to order parts via their parts department – MUST be **ZREC** order
11. For non GLX models - Dealer to replace the Mi-Display unit with the supplied Alpine unit, new microphone and external GPS antenna, then test all is OK.
    For GLX models only - replace harness to new Alpine unit (only until GLX harness parts are depleted), install Alpine unit, new microphone, external GPS antenna and fascia and test that all OK.
12. Remove and replace the audio unit user manual in the glove box.
13. Retain the removed Mi-Display unit for 90 days then destroy.

D

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Mi-Display to Alpine**		
Applicable Model(s)	MR Tritons fitted with a Mi-Display unit		
Notice Category	**Service Campaign**	Technical Bulletin	**020225**
Service Group	54 Chassis Electrical	Latest Revision Issued	20/08/2026
Revision	D	MMAL Reference	N/A

Campaign Claim Procedure

Submit a claim for this Service Campaign via the MMAL Warranty Portal.

Campaign	Claim Options	Labour Details	
		Operation	Time
020225	Mi-Display to Alpine (non GLX)	02022510	0.5H
	Mi-Display to Alpine (GLX harness)*	02022511	0.6H
	Mi-Display to Alpine (GLX unit)*	02022512	0.5H

*GLX has manual A/C controls (GLX+ and GLX-R have auto A/C and are Non GLX)

Ensure that the MiDealer Assist case number is noted in the chat section of the claim.

Ensure the correct option is claimed as per MMAL's instructions on the Mi-Dealer Assist case reply.

Revision Details

Initial Release – 16/12/2025
Revision A – Alternative process/parts for GLX models – 3/02/2026
Revision B – Clarification on MiDealer Assist process – 13/02/2026
Revision C – Clarification on "GLX" models – 16/07/2026
Revision D – Parts transition for GLX models

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
Commercial In Confidence

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.