MMAL DEALER BULLETIN

Bulletin Subject	**White stains on paint**		
Applicable model(s)	MV/MR Triton, QG Pajero Sport		
Notice Category	**Hotline Fix**	Technical Bulletin	**2025-023**
Service Group	42 Body	Latest Revision Issued	10/11/2025
Revision number	First	MMAL Reference	TSL2007010

Complaint

Stain on body panel paint due to humidity or liquid under protective wrap film.

Cause

Due to the improper wrap film installation, a bubble can form inside which traps moisture under the film and stays on the painted surface for a long period. This may cause “stains/milky spots" on the clear coat.



Correction

Dry the stain (milky spots) by ultraviolet heat lamp or hot air dryer.

Warning: Do not place heat lamps or hair dryer too close to the vehicle’s paintwork. Panel temperatures of 60°C or above can cause damage to the paint. Panel temperature should be closely monitored using an IR thermometer or similar.

DO NOT REPAINT THE VEHICLE OR AFFECTED PANELS FOR MOISTURE STAINING OF THE VEHICLE PAINT.

Warranty Information

Please submit the actual cost as warranty with photos for claim review.
Ensure photos are clear and clocking times are included.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**White stains on paint**		
Applicable model(s)	MV/MR Triton, QG Pajero Sport		
Notice Category	**Hotline Fix**	Technical Bulletin	**2025-023**
Service Group	42 Body	Latest Revision Issued	10/11/2025
Revision number	First	MMAL Reference	TSL2007010

⚠Printed copies may not reflect the latest updates. Please consult the online version.

Revision Details

1st edition – No revision applicable.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.