MMAL DEALER BULLETIN

Bulletin Subject	**Fuel Pump Module Malfunction**		
Applicable model(s)	MV Triton		
Notice Category	**Hotline fix**	Technical Bulletin	**2026-008**
Service Group	00 General	Latest Revision Issued	27/10/2026
Revision number	Second	MMAL Reference	SSI2601001-A

IMPORTANT: This Hotline Fix must be claimed using a Campaign Claim Type and repair approval must be obtained via TSR before carrying out this repair. Refer to the Warranty Information section at the bottom of this bulletin. Claims submitted with other claim types may be rejected or reversed during audit.

Complaint

The engine warning light being illuminated with DTC P008A-00 (Low Pressure Fuel System Pressure) set in the Engine ECU.

Cause

The contamination inside of the fuel tank from refuelling or other sources damages the fuel pump.

Production improvement

The internals of the fuel pump have been improved to increase resistance of the pump to damage from contaminants in the fuel.

Model	Production Fix Date	Improved from VIN
MV Triton	19/02/2026	MMAYLLC20TH001322

Correction

On a customer complaint basis - Replace the failed fuel pump with the revised part (as advised in the "Parts Information" section of this document) as per workshop manual instructions.

The fuel tank must also be cleaned during the repair in accordance with the attached "TRITON Fuel Tank Cleaning Procedure". Failure to follow this cleaning methodology may result in failure of the new fuel pump.

Please note.

This repair is performed for customer satisfaction for fuel pump damage due to contamination of the using fuel. As such it may be applied once per vehicle only on a customer complaint basis.

Any subsequent fuel pump concerns caused by contamination are subject to MMAL's standard warranty policy (refer to the vehicle's Service and Warranty Booklet, Warranty section "What is not covered"). Any such secondary claims must retain a fuel sample from both the fuel filter housing and the fuel tank for testing.

⚠**Printed copies may not reflect the latest updates. Please consult the online version**

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
General Information

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.

Bulletin Subject	**Fuel Pump Module Malfunction**		
Applicable model(s)	MV Triton		
Notice Category	**Hotline fix**	Technical Bulletin	**2026-008**
Service Group	00 General	Latest Revision Issued	27/10/2026
Revision number	Second	MMAL Reference	SSI2601001-A

Important: Care must be taken when removing and refitting the fuel tank and pump module – do not pull/stretch wiring harnesses or mis-handle/deform/damage connectors. Such actions may lead to poor connections and re-setting of DTC P008A-00 or other related Diagnostic Trouble Codes.

Parts Information

Part Name	Part Number	Qty
PUMP ASSY-FUEL	17011A050P	1

Note: This part is supplied as a kit, it includes the PACK FUEL GAUGE (O-RING) and FLANGE NUT, SELF LOCKING required for fitment.

Warranty Information

A TSR **is required** for all applicable cases, including all DTC and Freeze Frame Data (FFD) from the vehicle. To ensure that applicable DTC and FFD are accessible to TSR, please log into VDCS prior to reading DTCs from the vehicle – refer to Service Bulletin 2025-007 for details on VDCS log in.

Once the concern has been confirmed via TSR, the vehicle will have a repair campaign loaded against it for claiming purposes.

Note: As advised in the "Fuel Tank Cleaning Process" document, a minimum of 10L of filtered or new clean fuel is required for the cleaning process. If further fuel is needed for the cleaning process due to heavy contamination or extremely low fuel level, it is at the customer's expense.

Revision Details

2nd edition – Warranty information updated and claim warning added to page 1.

Disclaimer: The fact that a Workshop Instruction has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Note: Details contained in this Workshop Instruction and Attachments are current at the time of publication, MMAL however reserves the right to make changes at any time without prior notice or obligation. Printed copies may not reflect the latest updates. Please consult the online version.
General Information

Copyright © Mitsubishi Motors Australia Limited. Reproduction in whole or part prohibited.