ADVISORY HOTLINE FIX

Group: 54 - Electrical	**Original Date: 21st September 2015**	**No.** NW54-004, CJ54-009, MN54-007, PC54-005, LA54-003, XA54-006, ZJ54-004.
Model: NT/NW/NX Pajero, CJ Lancer, MN/MQ Triton, PC Challenger, LA Mirage, XA/XB ASX, ZJ/ZK	**Subject: Bluetooth pairing issues on vehicles fitted with the Mitsubishi Link Hands Free system.**	
Revised on 13/02/2018..... (date) **Revised on** ..... (date) **Revised on** ..... (date)	Yasuhiro Oda, Deputy Director, Aftersales	
MMAL Ref TSL1711067	**Document consists of 1 page**	

(1) **Subject**: Bluetooth pairing issues on vehicles fitted with the Mitsubishi Link Hands Free system.

(2) **Possible Cause**: Inconsistencies in phone software between manufacturers, 3rd party Applications and security programs can lead to pairing issues.

(3) **Improvement**: N/A.

(4) **Field Fix/Action**: Listed below is a suggested troubleshooting method for Bluetooth pairing concerns.

Find out what has changed – New car, new phone, updated phone firmware, new applications installed?

As we becoming aware, changes to phone firmware, installation of new applications or security software can change the behaviour of the phone and affect it's compatibility with other devices.

Please check the device compatibility via the Mitsubishi Link website -> www.mitsubishilink.com.au (ensure any pairing instructions in the "comments" section are followed) and ensure the phone is not connected via USB when connected or attempting to connect via Bluetooth. The phone should then be tested with a like system (ensure the Hands Free Module software number is the same). If the phone still cannot be paired, it can be determined that a compatibility issue exists with the device or it's installed software. Potential workarounds for this concern (please request customer permission before attempting the following) –

- Turn the phone and Bluetooth setting, off and back on again and retry the paring process.
- Leave the device Bluetooth off until the pairing password screen is displayed or the Bluetooth password is advised by the voice command system. Turn the Bluetooth on, scan for devices, select the Mitsubishi Hands Free system and enter the password.
- Clear the Bluetooth cache from the phone and known devices from the vehicle and retry the pairing process.
- For Android smart phones, trying installing the "Android Auto" Application from the Google Play store (free app), use a fixed pairing code of "0000" on the audio unit (refer to owner's manual for details on this process), and retry the pairing process.
- For phones with security programs and other 3rd party applications, a back-up of the phone / data / etc may need to be carried out followed by a master reset of the device. Once the phone has been returned to it's factory settings and proprietary applications, the paring process should be retried.

(5) Warranty: Information only. Warranty is not applicable for concerns related to 3rd party device software.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.