ADVISORY HOTLINE FIX

Group: 11 Engine	**Original Date:** 27 October 2017	**No.** MN11-002, PB11-002
Model: 4D56 Triton & Challenger	**Subject:** 4D56 Balance Shaft Breaks after engine works	
Revised on ..... (date) **Revised on** ..... (date) **Revised on** ..... (date)	Y Oda, Deputy Director, Aftersales	
MMAL Ref PQR No. 00KX141021682	**Document consists of 1 page**	

(1) **Subject:** The engine balance shaft breaks at the lubrication gallery section, after engine work has been performed.











(2) **Possible Cause:** Improper handling of the balance shaft during engine repairs, or excessive tension application to the balancer shaft/belt.

- Excessive force can be applied to the balance shaft by improper work, causing micro bending of the shaft.
- Excessive tension can be applied to the balance belt by improper work.
- Either of these issues cause high input loading to the shaft as the engine rotates, leading to eventual fatigue fracture of the shaft.

Note: The fatigue fracture can take many engine cycles before failure occurs. (e.g. 5-15,000 km)

(3) **Improvement:** N/A, information only.

(4) **Field Fix/Action:** N/A.

(5) **Parts and Warranty Information**: Not applicable for this concern.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.