Hotline Fix – MQ52-002, MR52-001

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Subject

Front seat cushion torn on Triton

Issued

29/06/2022

Previous Versions

03/10/2017

21/03/2018

21/06/2019

14/08/2019

15/07/2020

Group

52 – Interior & SRS

MMAL Reference

TSL2202007

Applicable Vehicles

Triton – All MQ & MR up to 22MY, with manual adjuster recliner and height adjustment.

Possible Cause

Due to wear occurring from the driver repeatedly getting in and out of the seat, the seat cover may prematurely wear due to the upper edge of the reinforcement felt pad touching the back/inner side of the seat cover. This may also lead to the stitching pulling apart on the outer portion of the seat base cover.

Production Fix

Effective 17/1/2019 - (Effective VIN: MMAJLKL10KH008708).

- To decrease stress between edge of felt and trim cover by changing reinforcing felt material to soften one.
- To enhance reinforcing resistance of trim cover by increasing thickness of lamination.

Effective 1/11/2021 – (Effective VIN: MMAWLKL10NH012143)

- Fabric strength has been improved by changing to new fabric type on the trim cover of front seat.

Disclaimer: The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
Copyright © Mitsubishi Motors Australia Limited

Hotline Fix – MQ52-002, MR52-001

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Field Fix/Action

On a customer complaint basis only, replace the driver's seat cover as per the WSM procedure.

If the front seat cushion pad is found damaged during repair, it should be replaced also.

Parts Information

Note: Refer to CAPS for original part number and use the below chart to cross reference.

Part Name	Part Number	Old Part Number	Quantity
Cover, FR Seat Cushion	87320W232P (SILVER-BLACK) 87320W231P (D/GREY-BLACK) 87320W233P (D/GREY-BLACK)	6911C050HB 6911C050XA 6911C050XB	1
Pad, Seat FR Cushion	6911D234 (RH)	NA	1

Warranty Information

Repairs performed in warranty that meet the preceding Hotline Fix conditions do not require SCA approval (unless it is a repeat repair). SCA's submitted for repairs not requiring prior approval may be cancelled.

Claim Details		
Claim Type	Warranty/Parts as applicable	
Position Code	521121	
Complaint Code	58	
Circumstance Code	As Advised by Customer	
Diagnosis Code	15	
Claim Items	**Replacement of cover and pad as a set (Driver side)**	**Replacement of cover only (Driver side)**
Main Labour Operation	521121GD	521121GF
Labour Qty	1	1
Spare Part Material (Causal Part –)	Cover, FR Seat Cushion – Refer to parts information table.	
Quantity	1	1
Spare Part Material	6911D234 – Pad, Seat Cushion	
Quantity	1	

Standard warranty terms and conditions apply.

Disclaimer: The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer internal use only. It must not be provided or supplied to third parties.
Copyright © Mitsubishi Motors Australia Limited