ADVISORY HOTLINE FIX

Group: 54 – Chassis Electrical	**Original Date: 03/10/2016**	**No. XB54-001**
Model: XB ASX	**Subject: RHS DRL and tail lamp inoperative and DTC B16A7 logged.**	
Revised on ..... (date) **Revised on** ..... (date) **Revised on** ..... (date)	Michael Miller Manager, Field Service	
MMAL Ref N/A	**Document consists of 1 page**	

(1) **Subject**: RHS DRL and tail lamp inoperative and DTC B16A7 logged.

(2) **Possible Cause**: If there is an open circuit in the glove compartment courtesy lamp circuit (due to a blown globe or wiring/connection issue), the ETACS ECU will detect a current draw abnormality and prohibit operation of the associated circuit (including the RHS DRL and tail lamp). DTC B16A7 may also be logged due to this concern.

(3) **Improvement**: N/A.

(4) **Field Fix/Action**: If a vehicle is presented with a complaint of the RHS DRL and tail lamp not working and/or DTC B16A7 logged, please inspect the glove compartment courtesy light globe for open circuit. If this globe is found to be ok, please inspect all associated wiring, using the wiring diagrams in the WSM as a guide.

(5) **Warranty Information:** Standard terms and conditions apply.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff

Copyright © Mitsubishi Motors Australia Limited
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.