Hotline Fix – ZM55-002 Rev B

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Subject

A

A/C system turns off unintentionally and does not turn back on automatically OR the A/C system turns off and back on automatically and some of the A/C settings such as the temperature have changed; on Outlander / Outlander PHEV.

Issued

30/05/2023

Previous Versions

06/03/2023

07/11/2023

Group

55 – Heater, Air Conditioner and Ventilation

MMAL Reference

A

TSL2207038-B

Applicable Vehicles

ZM Outlander / ZM Outlander PHEV

Phenomenon

A/C system turns off unintentionally. The A/C can be turned back on manually a few seconds later.

Or

A/C System turns off unintentionally and then turns back on automatically.

In both cases, some of the A/C settings such as temperature are likely to have changed.

Possible Cause

A

~~Internal communication error of A/C AUTO AMP~~.

Temporary communication disturbance causes the A/C-AMP microcomputer to reboot. When the microcomputer reboot occurs, the A/C system will turn off for a few seconds, after which it will restart with either:

- The last A/C setting selections at IG-OFF
- Default setting of 25 degrees, AUTO, A/C switch OFF.

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

Copyright © Mitsubishi Motors Australia Limited

Hotline Fix – ZM55-002 Rev B

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

⚠ **Printed versions of this document may be out of date, check the online version.**

Production Fix

A

~~Software modification, please see below table for VIN applicability.~~ *

*Table removed

1. Software modification to prevent a microcomputer reboot due to a temporary communication disturbance.
2. Software modification to maintain the current A/C setting if a microcomputer reboot occurs.

Implementation information TBA.

Field Fix/Action

A

~~On a customer complaint basis only, Update the software of A/C AUTO AMP (MUT3 displays "HVAC")~~

~~NOTE: MUT-~~Ⅲ~~ SE software ver. should be SDB_A221101 or later.~~
~~Refer to Service Bulletin 00-2022-013 - MUTIII software database update – SDB_A221101 and SDBN_A221002NR on the dealer portal.~~

B

On a customer complaint basis, replace the A/C-AMP with the countermeasure part according to the parts information table. Refer to the workshop manual for the A/C-AMP replacement procedure, then perform configuration of the new module and post repair self-diagnosis. **Reprogramming of the A/C AMP is not required**.

Note: A/C-AMP is displayed as HVAC on MUT3-SE.

Refer to New Model Introduction bulletin 00-2021-009 for information on configuration of the A/C-AMP

~~Software Information~~

A

*Table removed

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

Copyright © Mitsubishi Motors Australia Limited

Hotline Fix – ZM55-002 Rev B

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Parts Information

A

Model	Part name	Part number		Qty.	Remarks	
		New	Old			
Outlander / Outlander PHEV	AMPLIFIER, HVAC	27760W018P	27760W000P	1	DUAL A/C, **without** heated seat	Check the ECU label on the vehicle to identify corresponding new part number.
			27760W006P			
		27760W019P	27760W001P		DUAL A/C, **with** heated seat	
			27760W007P			
		27760W020P	27760W002P		TRIPLE A/C, **with** heated seat	
			27760W008P			

Location of part number on ECU label.



Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

Copyright © Mitsubishi Motors Australia Limited

Hotline Fix – ZM55-002 Rev B

Note: This document should be forwarded direct to the Service Manager for action and distribution to all affected staff.

Printed versions of this document may be out of date, check the online version.

Warranty Information

A

Claim Details			
Claim Type	Warranty		
Position Code	558515		
Complaint Code	59		
Circumstance Code	As Advised by Customer		
Diagnosis Code	5D		
Claim Items			
~~Main Labour Operation~~	~~558515HV~~		
Main Labour Operation	558515ME		
Labour Qty	1		
Labour Time	0.8 hr		
~~Miscellaneous Parts - Causal Part -~~	~~REFLASH~~		
Miscellaneous Parts - Causal Part -	DUAL A/C W heat	DUAL A/C WO heat	TRIPLE A/C W heat
	27760W018P	27760W019P	27760W020P
Quantity	1		

Standard warranty terms and conditions apply

Disclaimer: *The fact that a Hotline Fix has been issued does not express or imply that Mitsubishi Motors will apply or has any obligations to apply any product improvement or field fix to a vehicle that is out of warranty*.
Please note: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties.

Copyright © Mitsubishi Motors Australia Limited