





Ref. Models: KE640 KE640 Vario KED640

SERVICE TIP #E1

TROUBLESHOOTING DITTING KE640 ESPRESSO GRINDERS

DO NOT TAKE THE GRINDER APART BEFORE READING THE FOLLOWING:

PROBLEM	CHECK FOR	POSSIBLE SOLUTION
NO OUTPUT	THE SPOUT IS CLOGGED	Set grinding fineness to coarse and trigger
The grinder is spinning,	GRINDING IS SET TOO	the grind cycle. The grinder will grind itself
but coffee does not come	FINE	free. Afterwards, return the grind setting to
out		the desired fineness.
A FOREIGN OBJECT IS		Unplug the grinder. Clean the grinding
IN THE GRINDING		mechanism per manual instructions, and
CHAMBER		remove the foreign object.
THE GRINDER DOES	MAKE SURE THE	Plug the grinder in.
NOT TURN ON / THE	GRINDER IS PLUGGED IN	Check if the grinder's circuit breaker has
DISPLAY IS NOT LIT	THE OVERLOAD	been tripped and press, if appropriate. If
	PROTECTION HAS BEEN	the circuit breaker continues to trip,
	TRIPPED	contact your dealer.
	• THE WALL BREAKER HAS	Check the wall breaker and reset, if
	BEEN TRIPPED	appropriate.
TIME INCREMENT	WHEN ADJUSTING THE	Potentiometers and/or electronic board
SCROLLS ON ITS OWN	TIME INCREMENTS FOR	need to be replaced.
	SINGLE AND DOUBLE	
	SHOTS, THE NUMBERS	
	CHANGE UP AND DOWN ON	
	THEIR OWN ONCE YOU	
	TAKE YOUR FINGER AWAY	
THE CRINDER DOES	FROM THE DIAL	Dood the grip diagraphy
THE GRINDER DOES	THE GRINDING TIME IS SET	Reset the grinding time.
NOT GRIND, THE DISPLAY IS LIT, SINGLE-	TO ZERO	
CUP IS PRESELECTED		
GRINDING TOO	WORN OUT GRINDING	Replace the grinding discs.
SLOWLY and/or	DISCS	Tropiced the grinding diode.
OVERHEATING		

Visit our website at **www.ditting.com** for this and other service tips.