



PT. PJ-TEK MANDIRI

TECHNICAL INSPECTION & CERTIFICATION

Client	: PT Pertamina EP	Height of Mast	: 96 feet	
Rig ID	: RIG BW H35KD	Hook Load	: 97,5 Ton Metric	
Service	: Service Rig	Power	: 350 HP	
Type	: Mobil Rig	Place of Inspection	: Yard Lapes	
Manufacture	: IDECO	Date of Inspection	: 16 Mei 2026	
Year	: 1982	Rig Inspector	: Yandi Handiyan	
Model / Serial	: KM-96-215-GH			
DAILY INSPECTION CAT III REPORT				
No.	Equipment	Deficiencies	Categories	Remarks / Recommendation
1.	Upper Mast	  	Critical	Finding : Ditemukan 1 spot crack pada lasan L Beam 2 " x 2 " MPI Result : Discontinuity Acceptance Criteria : - API RP 4G Sect 6.2.3 Total Progress : 100% Recommendation : Segera lakukan perbaikan sesuai standar dan prosedur.
2.	Telescopic Mast		N/A	Finding : N/A MPI Result : No Discontinuity Acceptance Criteria : - API RP 4G Sect 6.2.3 Total Progress : 100%

3.	Make Up Tong		N/A	Finding : N/A MPI Result : No Discontinuity Acceptance Criteria : -API RP 4G Sect 6.2.3 Total Progress : 100
4.	Lower Mast		Major	Finding : Bent 3 Spot Struktur L Beam 2 "x 2" MPI Result : No Discontinuity Acceptance Criteria : -API RP 4G Sect 6.2.3 Total Progress : 100% Recommendation: Segera lakukan perbaikan dengan mengacu standard dan prosedur

5.	Locking Pawl		Critical	Finding : Ditemukan 2 spot crack lasan MPI Result : Discontinuity Acceptance Criteria : -API RP 4G Sect 6.2.3 -API RP 4G Sect 7.1 Total Progress : 100% Recommendation: Segera lakukan perbaikan sesuai standard dan prosedur.
6.	Hanging Manual Tong		Major	Finding : 1 Spot Crack MPI Result : Discontinuity Acceptance Criteria : -API RP 7L Sect 4.1.3 Total Progress : 100% Recommendation: Segera lakukan perbaikan atau pergantian sesuai spesifikasi

7.	Slip Spider 2 7/8"		Critical	Finding: 2 Spot crack pada bodi slip MPI Result: Discontinuity Acceptance Criteria: - API RP 7L Sect 4.1.3 Total Progress: 100% Recommendation: - Grinding surface crack dan MPI ulang - Segera lakukan pergantian sesuai spesifikasi.
8.	Bearing Sheave Dead Line 2ea		Critical	Finding : - Ditemukan 2 Spot korosi pada Bearing Sheave MPI Result : N/A Acceptance Criteria : - API RP 7L Sect 6.3 Total Progress : 100% Recommendation: Segera lakukan pergantian sesuai spesifikasi
	Escape Chair		Critical	Finding : - Ditemukan 1 Spot crack MPI Result : N/A Acceptance Criteria : - API RP 54 Total Progress : 100% Recommendation: Segera lakukan perbaikan sesuai standard dan prosedur.

No.	Category	Total Finding
1.	Major	2
2.	Critical	5
Total		7

Keterangan :

1. Critical :

Kerusakan dan kegagalan peralatan dan ketidaksesuaian spesifikasi yang ditentukan sehingga dapat menyebabkan kerusakan area atau nyawa manusia. Umumnya pada wilayah komponen- Komponen yang menerima beban utama proses pengeboran.

2. Major :

Kerusakan atau kegagalan peralatan akibat ketidaksesuaian spesifikasi yang ditentukan sehingga dapat merusak peralatan utama atau menghambat operasi.

Progres pekerjaan H3- 15%

Akumulatif : 35%

Dibuat oleh :

PT PJ-Tek Mandiri



Yandi Handiyan

Disetujui:

PT Pertamina EP