USM BACK-TO-BIRTH TRACE PRE-AUDIT EXCEPTION REPORT

Docket: AUD-DEMO-AOG-TECHNICS-FORGERY-1793732979 | **Date:** 2026-11-03 | **Auditor:** USM Trace Exception-Audit Desk v1.0 | **Authority:** FAA Order 8130.21J / AC 43-9D

AUDIT STATUS: REJECT — SUP ALERT / QUARANTINE MANDATORY — Score: 0.0/100

1. Article Specifications & Life-Limited Part (LLP) Tracking

Part Number:	322-049-204-0	**Serial Number:**	SN-FORGED-001
Description:	bushing	**LLP Classified:**	NO (On-Condition)
Current TSN (Hours):	N/A	**Current CSN (Cycles):**	N/A
Mandatory Limit:	N/A	**Remaining Cycles:**	**N/A**

2. Audit Findings & Red Flags (4 Discrepancies)

ID / Sev	Doc / Block	Regulatory Rule / Finding	Required Action
EXP-SUP-BLRPLATE-DOC-FORGED-8130 CRITICAL	**DOC-FORGED-8130** Boilerplate Notice	**Document lacks mandatory installer/user responsibility disclaimer on face or reverse.** *FAA Order 8130.21J para 3-3 & Appendix A / FAA SUP Notice (AOG Technics)* AOG Technics forged release forms systematically omitted or truncated the mandatory installer responsibility legal notice. Unapproved template detected.	QUARANTINE PART IMMEDIATELY. Suspected Unapproved Part (SUP) alert; verify airworthiness tag directly with issuing CRS or FAA FSDO.
EXP-SUP-BLK13-NOTSHADED-DOC-FORGED-8130 CRITICAL	**DOC-FORGED-8130** Block 13	**Block 13 is not shaded/grayed out despite maintenance release executed in Block 14.** *FAA Order 8130.21J para 3-7(f) / FAA SUP Advisory* Failure to shade unused Block 13 allows fraudulent post-release endorsement.	Hold delivery. Require issuing repair station to provide properly formatted release.
EXP-SUP-NOMENCLATURE-DOC-FORGED-8130 MAJOR	**DOC-FORGED-8130** Block 7	**Block 7 description 'bushing' does not match official CFM International IPC nomenclature 'BUSHING SHRD (IGV)'.** *FAA SUP Notice 2023 / CFM International Advisory Notice* Part number 322-049-204-0 corresponds to official OEM nomenclature 'BUSHING SHRD (IGV)'. Generic colloquial term 'bushing' matches forged tag profile.	Quarantine article. Cross-examine illustrated parts catalog and demand OEM trace.
EXP-SUP-CERT-MISMATCH-14-DOC-FORGED-8130 CRITICAL	**DOC-FORGED-8130** Block 4 & Block 14c	**Issuing organization certificate in Block 4 ('CRS FAKE123A') does not match Block 14c certificate ('CRS MISMATCH999B').** *FAA Order 8130.21J para 3-7(d) / AOG Technics SUP Precedent* In maintenance releases, Block 14c MUST record the certificate number of the organization named in Block 2 and Block 4. Mismatch indicates unauthorized or fraudulent signature.	QUARANTINE. High probability of fraudulent airworthiness approval. File FAA Form 8120-11 SUP report.

3. Back-to-Birth Custody & Flight Accumulation Chronology

Date	Doc ID / Type	Releasing Entity / Operator	TSN (Hrs)	CSN (Cyc)	Event / Status Summary
2026-02-15	**DOC-FORGED-8130** FORM_8130_3	AOG Technics Ltd / Fictitious Agency	-	-	8130-3 (OVERHAULED)

4. Quality Assurance Disposition & Sign-off Block

Pre-Audit Determination:	**REJECT_SUP_ALERT (Score: 0.0/100)**	**Audit Date:**	2026-11-03
Audited By:	USM Trace Exception-Audit Desk v1.0	**QA Inspection Seal:**	**[CERTIFIED PRE-AUDIT DOSSIER]**

Disclaimer: This autonomous pre-audit docket provides automated regulatory compliance screening per FAA Order 8130.21J, AC 43-9D, and AC 120-84. The certified installer or certificated agency maintains ultimate responsibility for airworthiness determination prior to aircraft installation.