

## 3.044 MATERIALS PROCESSING

## LECTURE 11


## Solidification of Multicomponent Liquids






single component system: single  $T_m$ 

multicomponent system: solidify over a range of  ${\cal T}$ 








Date: March 19th, 2012.


2


1. Assume: equilibrium solidification (rapid diffusion in both liquid and solid)













Key Lesson: phase transformations push solute around

Conservation of Solute: Lever Rule:  $c_0 = f_s \cdot c_s + f_l \cdot c_l$ 


2. More realistic assumption: diffusion is fast in liquid and non-existent in solid





grains

## Solute Balance:



$$(c_l - c_s^*) df_s = f_l \cdot dc_l$$

$$(c_l - c_s^*) df_s = (1 - f_s) \cdot dc_l$$

$$\frac{df_s}{1 - f_s} = \frac{dc_l}{c_l - c_s^*}$$

B.C. 
$$@f_s = 0 : c_l = c_0 \& c_s^* = c_{s,1}$$

 $\underline{\text{Define } k:}$  partition coefficient

$$k = \frac{c_s}{c_l}$$

6 LECTURE 11

- · from phase diagram, k describes the width of a 2-phase field
- $\cdot$  k is a materials constant if and only if the solidus and liquidus are lines
- · first solid to form is of composition  $c_{s,1}$

$$c_{s,1} = kc_0$$
$$c_s^* = c_{s,1} = kc_0$$

Solve: Non-Equilibrium Lever Rule

$$c_S^* = kc_0(1 - f_s)^{(k-1)}$$
 or  $c_l = c_0 f_l^{(k-1)}$ 

 $\Rightarrow$  The Non-Equilibrium Lever Rule applies to stirred liquids, rapid diffusion in liquid, slow solid diffusion

3.044 Materials Processing Spring 2013

For information about citing these materials or our Terms of Use, visit: http://ocw.mit.edu/terms.